

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Feb 2022)

Parts: M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SJU8218H/16/02/2022 14:35

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No. Qty Part No. Particulars

%Disc %Depr Amount

1	1	*FRONT LH DOOR							
2	1	*FRONT LH DOOR OUTER HANDLE							
3	1	*FRONT LH DOOR HINGE TOP							
4	1	*FRONT LH DOOR HINGE LOWER							
5	1	*FRONT LH DOOR FRAME BLACK STICKER(REAR)							
6	1	*FRONT LH DOOR FRAME BLACK STICKER(TOP)							
7	1	*FRONT LH DOOR FRAME BLACK STICKER(FRONT)							
8	1	*FRONT LH DOOR GLASS OUTER MOULDING							
9	1	*FRONT LH DOOR WEATHER STRIP							
10	1	*LH WING MIRROR WITH BODY	330	repair					
11	1	*LH WING MIRROR SIGNAL LAMP							
12	1	*LH FRONT FENDER							
13	1	*LH FRONT FENDER CORNER COVER							
14	1	*LH FRONT FENDER INNER SHIELD							
15	8	*LH FRONT FENDER INNER SHIELD CLIP							
16	1	*FRONT BUMPER LH SIDE RETAINER							
17	1	*FRONT BUMPER							
18	1	*LH ENGINE TOP SIDE TRIM							
19	5	*LH ENGINE TOP SIDE TRIM CLIP							
20	1	*BONNET							
21	12	*BONNET INSULATOR CLIP							

F=Franchise part.

1 headlamp LH Bro ✓ 1400

Sub Total (\$)

3,108.50

+ Margin on L,N Items 10.00% (\$)

310.85

Total Parts (\$)

3,419.35

ComfortDelGro Engineering Pte Ltd/SJU8218H/16/02/2022 14:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

2012.50

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO JACK,STRAIGHTEN ON LH FRONTFENDER INNER PANEL,A PILLAR ,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	800l 1,000.00
2	TO PUTTY,RESPRAY ON FRONT BUMPER,LH FRT FENDER,INNER PANEL,A PILLAR ,LH FRT DOOR ,LH REAR DOOR AND AFFECTED AREAS	New	1100l 1,300.00
3	CHECK LIGHTING AND WIRING	New	20l 30.00
4	TO REMOVE,TRANSFER PARTS TO NEW DOOR	New	80l 150.00
5	CHECK AND ADJUST WHEEL ALIGNMENT	New	nn 60.00 X
6	REPLACE AND RESPRAY WING MIRROR LH	New	nn 80.00 X
Gross Labour Cost (S\$)			2,620.00

ComfortDelGro Engineering Pte Ltd/SJU8218H/16/02/2022 14:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

TD: Veron

2000

Parts = 2012.50

Supp 1 = 1400.00

Supp 2 = 300.00 X

= 3712.50

+10% 371.25

= 4083.75

+ Labour 2000.00

= 6083.75

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3412.50

+10% 341.25

3753.75

2000

5753.75

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 Feb 2022)**Parts:** M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SJU8218H/28/02/2022 17:18**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LH HEADLAMP	0.00	0.00	Prv 1,400.00 F ✓
			Sub Total (S\$)			1,400.00
			+ Margin on L,N Items 10.00% (S\$)			140.00
			Total Parts (S\$)			1,540.00

ComfortDelGro Engineering Pte Ltd/SJU8218H/28/02/2022 17:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Sep 2022)

Parts: M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SJU8218H/20/09/2022 13:30

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT LOCK MODULE	0.00	0.00	*300.00 F
Sub Total (\$)						300.00
+ Margin on L,N Items 10.00% (\$)						30.00
Total Parts (\$)						330.00

F=Franchise part.

ComfortDelGro Engineering Pte Ltd/SJU8218H/20/09/2022 13:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

X