

Date: 21/02/2022

Insurance: NTUC

MVA: MS. LOKE YY

Page 1

REAR FENDER ADVERTISEMENT LOGO LH			\$100.00	Nett	net x
REAR FENDER ADVERTISEMENT LOGO RH			\$100.00	Nett	net x
BOOTLID ADVERTISEMENT LOGO			\$100.00	Nett	net x
BOOTLID CITYCAB LOGO & TEL NO STICKER	-10%		\$60.00	Nett	net x
REAR BUMPER REVERSE SENSOR	-10%		\$135.70	Nett	net
REAR NUMBER PLATE	-10%		\$25.00	Nett	X net
			\$570.70	Nett	
Labour Charge					
PANEL BEATING			\$1,200.00		700
SPRAY PAINTING CHARGE			\$750.00		9 ✓
CHECK ALL LIGHTING			\$60.00		30
TUFF KOTE			\$60.00		30
REMOVE/REFIX REVERSE SENSOR			\$60.00		30
TOTAL LABOUR			\$2,130.00		1540
ESTIMATE TOTAL			\$11,512.48		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

3433.26
 122.13
 1540
 5095.39
 4544050
 3 days #

Tanjin 9749540
 WP 21/7/22 @ 4:00pm
 AS Newy stamp
 3 days
 Tanjin C. Khan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: