

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001683/ENY3E2
Date: 13/04/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPSCNA00168472101
Claimant Vehicle No :	FBL8211T	Insured Vehicle No :	SMU9786S
Date of Loss:	08/01/2022	Nature of Claim:	TP
		Claim No:	SNM22D200239/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL8211T	Engine No:	RC88E5011703
Make & Model:	HONDA NC750XA, 745cc	Chassis No:	JH2RC90AXHK102778
Reg. Date:	03/04/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	745 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/55 R17	Rear Tyre Size:	140/55 R17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,819.00	5,175.00	4,644.00	47.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	747.50	290.00	457.50	61.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,566.50	5,465.00	5,101.50	48.28
Approved Total (Overridden) (S\$)		4,400.00		
(S\$)	10,566.50	4,400.00	6,166.50	58.36
+ GST 8.00/8.00% (S\$)	845.32	352.00	493.32	58.36
Nett Amount (S\$)	11,411.82	4,752.00	6,659.82	58.36

INSPECTION

Date of Assignment:	21/02/2022	
Date Inspected:	22/02/2022	Inspected At: Southern Motor (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10 Singapore 159762
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Apr 2023)	
Parts:	N/A	HONDA NC750XA 745cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL8211T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SPORT RIM	Bent	1,350.00 FL	*650.00 FL
2	1		*FRONT BRAKE DISC	Not Necessary	280.00 FL	*- FL
3	1		*FRONT FORK	Bent	2,700.00 FL	*1,000.00 FL
4	1		*FRONT MUDGUARD	Broken	285.00 FL	*285.00 FL
5	1		*FRONT HEADLAMP	Cut	480.00 FL	*480.00 FL
6	2		*SET CENTRE FAIRING RH / LH	Cut	1,600.00 FL	*800.00 FL
7	1		*RADIATOR	Dented	1,200.00 FL	*550.00 FL
8	1		*ENGINE GUARD	Dented	450.00 FL	*350.00 FL
9	1		*HANDLE BAR	Bent	230.00 FL	*230.00 FL
10	1		*HANDLE GUARD	Cut	250.00 FL	*250.00 FL
11	1		*REAR HEPKO & BECKER BOX	Broken	850.00 FL	*800.00 FL
12	1		*EXHAUST PIPE	Repair	880.00 FL	*- FL
13	1		*CLUTCH CABLE	Torn	65.00 FL	*65.00 FL
14	1		*CLUTCH CABLE HOLDER	Bent	45.00 FL	*45.00 FL
15	1		*LOWER COWLING RH	Cut	220.00 FL	*220.00 FL
16	1		*HORN	Bent	25.00 FL	*25.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	10,910.00	5,750.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,091.00	575.00
Total Parts (\$\$)	9,819.00	5,175.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT	New	40.00	40.00
2	LTA FEES	New	7.50	0.00
3	ALIGNMENT BODY	New	350.00	0.00
4	LABOUR	New	350.00	250.00
Gross Labour Cost (\$\$)			747.50	290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >