



南方摩哆

Southern Motor

Business Reg. No: 234147/00L

Block 1006, Bukit Merah Lane 2, #01-10, Singapore 159762

Tel: 6273-0369 (3 Lines) Fax: 6274-6614

21-Feb-22

China Taiping Insurance Singapore Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore (079909)

Dear Sirs,

Steve (LKK)
22/2/22, 10.00

8322 8813

W R
4 dy
L/S
Hy 11/11

RE: Cost of repair to Honda NC750X - FBL8211T

1pc of Front Sport Rim / BT	SS	1,350.00
1pc of Front Brake Disc X		280.00
1pc of Front Fork / BT		2,700.00
1pc of Front Mudguard / BR		285.00
1pc of Front HeadLamp / CMT		480.00
2Set of Centre Fairing RH/LH / CMT		1,600.00
1pc of Radiator / DO		1,200.00
1pc of Engine Guard / DO		450.00
1pc of Handle Bar / BT		230.00
1pc of Handle Guard / CMT		250.00
1pc of Rear Hepco & Becker Box / BR		850.00
1pc of Exhaust Pipe X R		880.00
1pc of Clutch Cable / TN		65.00
1pc of Clutch Cable Holder / BT		45.00
1pc of Lower Cowling RH / CMT		220.00
1pc of Horn / BT		25.00
		10,910.00
		1,091.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Less 10%

Nett

Transport

LTA Fees

Alignment Body

Labour

9,819.00

40.00 / MC

7.50 / MC

350.00

350.00 250

\$10,566.50

Yours Faithfully,

Southern Motor

