



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22001694/Etf3e2	
			Date: 01/04/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 6437P	Veh. Inspected	JRC 5013
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22000515MFCV	Excess (\$)	0.00
	Assign From	JOANNE TAN JO ANN	Assign Date	22/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA 135 LC	c.c	135
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	PMYUG0410F0299103	Colour	BLACK
	Odometer	50042 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	60/70-17	DUNLOP	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	70/80-17	DUNLOP	4 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	19/02/2022	Inspection Date	22/02/2022
	Survey held at	KIM KOCK MOTOR PTE LTD BLK 27A JURONG PORT ROAD #01-19 SINGAPORE 619101		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	