

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 4256L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	LR FRONT BUMPER ASSEMBLY EVOQUE	BUCKLED / CRACKED	2,732.00	2,450.00
1	LR FRONT BUMPER UPPER IMPACT ABSORBER EVOQUE	CRACKED	732.00	732.00
1	LR FRONT BUMPER REINFORCEMENT BAR EVOQUE	TO REPAIR SEE LABOUR	1,310.00	-
1	LR FRONT BUMPER SIDE BRACKET LH EVOQUE	DISTORTED	82.00	82.00
1	LR FRONT BUMPER SIDE BRACKET RH EVOQUE	DISTORTED	82.00	82.00
1	LR FRONT BUMPER LOWER DEFECTOR EVOQUE	DENTED / CUT	890.80	656.00
2	LR FRONT BUMPER PARKING SENSOR CENTER EVOQUE @\$280.00	SERVICEABLE	560.00	-
2	LR FRONT BUMPER PARKING CENTER CAP @\$25.00	SERVICEABLE	50.00	-
	LESS 10% DISCOUNT		-	-400.20
			6,438.80	3,601.80
	SPECIAL NETT ITEMS			
1	NUMBER PLATE WITH HOLDER (SN)	BENT	80.00	45.00
			80.00	45.00
	<u>LABOUR</u>			
	TO REMOVE,INSTALL,REPLACE FRONT BUMPER,FRONT BUMPER BRACKET,FRONT UPPER IMPACT ABSORBER,BUMPER REINFORCEMENT,LOWER PROTECTOR,BUMPER PARKING CENTER CENTER.INCLUSIVE OF THE REPAIR OF LR FRONT BUMPER REINFORCEMENT BAR EVOQUE.		800.00	300.00
	TO SPRAY PAINTING FRONT BUMPER,BUMPER OUTER PROTECTOR.		800.00	480.00
			1,600.00	780.00
	GRAND TOTAL		8,118.80	4,426.80



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,500.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/SMR22001699/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser