

Submit

not allowed
dur

CHOO MOTOR SPRAY PAINTER
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
SINGAPORE 417883

2/s 3800/
22/2/22

take photo after repair
3 days.

VEHICLE No: SLJ 7153B

1PC	FRONT BUMPER	wo/se	819.40	\$911.20	✓
1PC	FRONT BUMPER FOG LAMP O/S	one	282.30	\$450.00	✓
1PC	FRONT BUMPER FOG LAMP GARNISH O/S	groz	105.20	\$182.30	✓
1PC	FRONT BUMPER SENSOR	n1		\$220.00	X
1PC	FRONT BUMPER SIDE RETAINER O/S	neu	45.50	\$65.50	✓
1PC	FRONT BUMPER BEAM	so		\$288.40	✓
1SET	FRONT BUMPER CLIPS	neu		\$40.00	✓
1PC	FRONT GRILLE ASSY	scr/one	680.30	\$1,220.30	✓
1PC	FRONT FENDER O/S	R		\$845.20	X
1PC	HEADLAMP O/S	holder one	2433.60	\$2,655.30	✓
1PC	HEADLAMP BRACKET O/S	one		\$68.50	✓
1PC	FRONT LICENCE PLATE	scr		\$50.00	✓
1PC	FRONT SUPPORT PANEL	R		\$655.20	X
				\$7,651.90	

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX FRONT BUMPER SENSOR	\$80.00	40
TO REFILL AIR CON GAS	\$120.00	X
TO SPRAY RUST PROOFING	\$50.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$680.00	350
TO PUTTY & SPRAY PAINTING	\$900.00	500
TOTAL	\$9,531.90	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p- 4813-2
202
93850.56
2- 910
4760.56
202
3808