

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2022)
Parts:	143	BMW 540I 3.0 SR LED NAV HUD RCP MSPORT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK108K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
						1,687.10
1	1		*FRONT BUMPER ✓	Broken	2,569.00 FL	*1,928.00 FL
2	1		*SET FRONT BUMPER CLIPS ✓	Necessary	70.00 FL	*30.00 FL
3	1		*FRONT BUMPER RH SIDE DISTANCE SENSOR ✓	Short Circuit	286.00 FL	*238.00 FL
4	1		*FRONT BUMPER RH SIDE CORNER DISTANCE SENSOR ✓	Short Circuit	286.00 FL	*238.00 FL
5	6		*FRONT BUMPER DISTANCE SENSOR SEAL ✓	Necessary	33.00 FL	*33.00 FL
6	1		*FRONT BUMPER RH SIDE GARNISH X	Broken	97.00 FL	*97.00 FL
7	1		*FRONT BUMPER RH SIDE GARNISH GRILLE ✓	Broken	86.00 FL	*86.00 FL 76.60
8	1		*FRONT BUMPER RH LED LAMP	Not Damaged	435.00 FL	*- FL
9	1		*FRONT BUMPER RH SIDE RETAINER ✓	Necessary	88.00 FL	*67.00 FL
10	1		*RH HEADLAMP ASSY X	Broken	4,988.00 FL	*4,281.00 FL
11	1		*RH FRONT FENDER X Repair	Bent	1,009.00 FL	*863.00 FL
12	1		*RH FRONT FENDER EMBLEM ✓	Necessary	67.00 FL	*67.00 FL
13	1		*RH FRONT FENDER LOWER GRILLE	Not Damaged	101.00 FL	*- FL
14	1		*RH FRONT FENDER SPLASH SHIELD (FRONT)	Not Damaged	156.00 FL	*- FL
15	1		*RH FRONT SPORT RIM (ORIGINAL)	Not Necessary	1,168.00 FL	*- FL
16	1		*RH FRONT LOWER ARM	Not Damaged	708.00 FL	*- FL
17	1		*RH FRONT KNUCKLE ARM	Not Damaged	1,236.00 FL	*- FL
18	1		*RH FRONT WHEEL BEARING	Not Damaged	562.00 FL	*- FL
19	1		*RH FRONT SHOCK ABSORBER	Not Damaged	558.00 FL	*- FL
20	1		*RH FRONT CONTROL ARM	Not Damaged	532.00 FL	*- FL
21	1		*SET RH FRONT FENDER SPLASH SHIELD CLIPS	Not Damaged	70.00 FL	*- FL
22	1		*RH FRONT TYRE	Not Damaged	550.00 FS	*- FS
23	1		*BRAKE FLUID	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,735.00	7,928.00
- List Item Discount on L Items 5.00/10.00% (S\$)	755.25	792.80
Total Parts (S\$)	14,979.75	7,135.20

Report was unsubmitted during this print-out.

Parts: 2,193.03
Labour: 600.00
Painting: 400.00
Total: 3,193.03
Lumpsum: 2,550.00