

Company Reg No: 201929175W

Chassis number: WBAJB32080WW37600

BR ✓
NEC ✓
SC ✓
NEC ✓
BR ✓
BR ✓
NDX
NEC ✓
BR ✓
BT ✓
NEC ✓
} NDX
~~CUT~~ ✓
} NDX

NDA
NNX

		Total	\$ 630.00

	Labour and painting		Amount
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	600.00	\$ 1,000.00
2	Spray painting on affected areas and panels	400.00	\$ 1,000.00
3	Check wiring and lighting system		\$ -80.00
4	Apply rust coating chemical on affected areas and panels		\$ -80.00
5	Remove and replace front undercarriage parts		\$ 450.00
6	Test drive and adjust wheel alignment system		\$ 120.00
		Total	\$ 2,730.00

Survey & Resurvey not necessary
only external damages

24/2/2022

Porium has

1350 hrs

Lump sum repair
Repair days 6

Spare Parts:	\$	14,349.75
Special Nett:	\$	630.00
Labour:	\$	2,730.00
Total Amount:	\$	17,709.75

Parts	8291.60
SN	-
Labour	<u>1200.00</u>
	9291.60
@ 20%	<u>1858.32</u>
	7433.28

LS 7450 1/2

TGününün
18/4/2022

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: