



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21012003/Rtf3e2-1 Date: 08/03/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GX 7804S	Veh. Inspected	SMG 8683K
	Policy No.		Coverage (\$)	0.00
	Claim No.	212121VC00025180	Excess (\$)	0.00
	Assign From	KENNY LIM	Assign Date	22/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HARRIER	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JTEKB3GH00J004054	Colour	BLACK
	Odometer	47017 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R18	YOKOHAMA	6 mm
	L/H Front Tyre	235/55 R18	YOKOHAMA	6 mm
	R/H Rear Tyre	235/55 R18	YOKOHAMA	6 mm
	L/H Rear Tyre	235/55 R18	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/11/2021	Inspection Date	30/11/2021
	Survey held at	833 MOTORSPORTS BLK 20 SIN MING IND.EST.SECTOR A #01-16 SINGAPORE 575678		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	