

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 22 Feb 2022

**Preliminary Advice**

Vehicle No	: SMQ626B	Accident Date	: 10/02/2021
Make	: MERCEDES- BENZ E220D SE	Policy No.	: DMHCSNW00002272101
Assignment Date	: 22/02/2022	Excess	: S\$1,250.00
Date of Inspection	: 22/02/2022	Est. Duration of Repair	: 30
Inspection At	: DING AUTO PTE LTD (HQ) 176 SIN MING DRIVE #04-06, SIN MING AUTOCARE SINGAPORE 575721		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 83,143.34
Revised Amount	:S\$ 58,969.34
Check Items (Estimated)	:S\$ 24,090.00
Total	:S\$ 83,059.34

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$ 170,000.00
COE / PARF Rebate	:S\$ 83,055.00

Salvage Value	:S\$
Margin for Repair	:S\$ 86,945.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Repairer declare that SMQ 626B is beyond economical for repair due to foreseen further supplementary or serious damages.