

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22001709/KVF3E2

Date: 10/05/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001960496		
Claimant Vehicle No :	SMA9479J	Insured Vehicle No :	SLL6615G		
Date of Loss:	17/02/2022	Nature of Claim:	TP	Claim No:	269954

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA9479J	Engine No:	L15B5551611
Make & Model:	HONDA VEZEL, 1.5 1.5X CVT (A)	Chassis No:	RU11301607
Reg. Date:	25/06/2018 (Man. Year: 2018)	Odometer:	73941 km
Colour:	Matt Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,455.52	1,301.44	154.08	10.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,080.00	670.00	38.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,205.52	2,381.44	824.08	25.71
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	3,205.52	1,900.00	1,305.52	40.73
+ GST 7.00/7.00% (S\$)	224.39	133.00	91.39	40.73
Nett Amount (S\$)	3,429.91	2,033.00	1,396.91	40.73

INSPECTION

Date of Assignment:	22/02/2022	Chew Goon Motor (AMK)
Date Inspected:	23/02/2022 Inspected At:	Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Estimated Period of Repair:	4.0 days	Singapore 568047

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Apr 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA9479J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Cracked	892.00 FL	*762.70 FL
2	12		*REAR BUMPER CLIPS	Necessary	45.60 FL	*45.60 FL
3	1		*REAR BUMPER TOP RETAINER RH	Serviceable	28.00 FL	*- FL
4	1		*REAR BUMPER REFLECTOR RH	Cut	155.70 FL	*155.70 FL
5	1		*REAR BUMPER CORNER RETAINER RH	Distorted	18.00 FL	*18.00 FL
6	1		*REAR BUMPER SIDE COVER RH	Buckled	204.30 FL	*195.00 FL
7	10		*REAR FENDER ARCH PROTECTOR CLIPS	Necessary	45.00 FL	*45.00 FL
8	1		*REAR FENDER SHIELD RH	Cracked	109.00 FL	*109.00 FL
9	10		*REAR FENDER SHIELD CLIPS	Necessary	45.00 FL	*45.00 FL
10	1		*TAILGATE EMBLEM	Not Necessary	26.00 FL	*- FL
11	1		*TAILGATE BADGE VEZEL	Necessary	45.80 FL	*45.80 FL
12	1		*REAR FENDER ARCH PROTECTOR RH	Buckled	205.00 FL	*205.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,819.40	1,626.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	363.88	325.36
Total Parts (\$\$)	1,455.52	1,301.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE - PANEL BEATING, REPAIRING OF TAILGATE, END PANEL, REAR FENDER & PART REPLACEMENT	New	550.00	280.00
2	TO SPRAY PAINT AFFECTED AREAS (MATT BLACK) (BOOT, BUMPER, FENDER, END PANEL)	New	1,200.00	800.00
Gross Labour Cost (\$\$)			1,750.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >