

REF: MSG/22001709/KV

趙源摩托 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AXA Insurance (S) Pte Ltd

Not Notified
618pm 81900hr
Penny After Pam
4 days

Policy No: Third Party

Date: 21.02.2022

Accident Date : 17.02.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Honda Vezel" Reg. No. SMA9479J Claiming Against Your Insured Veh. No. SLL6615G		
1pc	Rear Bumper <i>762.70</i>		<i>892.00</i> ✓
142cs	Rear Bumper Clips	3.80	<i>45.60</i> ✓
1pc	Rear Bumper Top Retainer RH		<i>28.00</i> ✓
1pc	Rear Bumper Reflector RH		<i>155.70</i> ✓
1pc	Rear Bumper Corner Retainer RH		<i>18.00</i> ✓
1pc	Rear Bumper Side Cover RH <i>195</i>		<i>204.30</i> ✓
1pc	Rear Fender Arch Protector RH		<i>205.00</i> ✓
10pcs	Rear Fender Arch Protector Clips	4.50	<i>45.00</i> ✓
1pc	Rear Fender Shield RH		<i>109.00</i> ✓
1pc	Rear Fender Shield Clips	4.50	<i>45.00</i> ✓
1pc	Tailgate Emblem		<i>26.00</i> X
1pc	Tailgate Badge Vezel		<i>45.80</i> ✓
			1,819.40
			363.88
			1,455.52
	Less 20%		
	Labour Charge - Panel Beating, Repairing of Tailgate, End Panel, Rear Fender & Part Replacement		550.00 <i>2801</i>
	To Spray Paint Affected Areas (Matt Black) (Boot, Bumper, Fender, End Panel)		1,200.00 <i>800</i>
	Total :		3,205.52

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tech Invs (S)