

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22001710/KPA3Q2**Date:** 08/06/2022REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 7210003402   |
| <b>Claimant Vehicle No :</b> | SLA9535S                             | <b>Insured Vehicle No :</b> | SMX4894E     |
| Date of Loss:                | 20/02/2022                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 4960754985SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLA9535S</b>                   | Engine No:  | 1ZR556916         |
| Make & Model:               | TOYOTA COROLLA ALTIS, 1.6 CVT (A) | Chassis No: | MR053REH104546888 |
| Reg. Date:                  | 23/03/2016 (Man. Year: 2015)      | Odometer:   | 32777 km          |
| Colour:                     | Metallic Silver                   |             |                   |
| Engine Capacity:            | 1598 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |             |
|-------------------|---------------|------------------|-------------|
| Front Tyre Size:  | 205/55 R16    | Rear Tyre Size:  | 205/55 R16  |
| Front Left Side:  | Yokohama 9 mm | Rear Left Side:  | Dunlop 8 mm |
| Front Right Side: | Yokohama 9 mm | Rear Right Side: | Dunlop 8 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 5,341.90          | 3,913.82          | 1,428.08          | 26.73         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 2,100.00          | 1,620.00          | 480.00            | 22.86         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>7,441.90</b>   | <b>5,533.82</b>   | <b>1,908.08</b>   | <b>25.64</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>4,400.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 7,441.90          | 4,400.00          | 3,041.90          | 40.88         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 520.93            | 308.00            | 212.93            | 40.87         |
| <b>Nett Amount (S\$)</b>                        | <b>7,962.83</b>   | <b>4,708.00</b>   | <b>3,254.83</b>   | <b>40.88</b>  |
| <b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b> |                   | 360.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 2.00              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>5,070.00</b>   |                   |               |

INSPECTION

|                             |            |                                                                                                               |
|-----------------------------|------------|---------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 22/02/2022 |                                                                                                               |
| Date Inspected:             | 22/02/2022 | Inspected At: Alan's United Auto Pte Ltd (HQ)<br>Blk 7 Sin Ming Industrial Estate, #01-76<br>Singapore 575642 |
| Estimated Period of Repair: | 6.0 days   |                                                                                                               |

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                 | Condition    | Repairer's | Amount     |
|-----|-----|----------|-----------------------------|--------------|------------|------------|
| 1   | 1   |          | *BOOT LID                   | Bent         | 754.30 FL  | *754.30 FL |
| 2   | 1   |          | *BOOT LID INNER LOCK        | Dented       | 382.20 FL  | *382.20 FL |
| 3   | 1   |          | *BOOT LID RUBBER (50%)      | Cut          | 124.80 FS  | *83.20 FS  |
| 4   | 2   |          | *BOOT LID HINGE             | Repair       | 155.60 FL  | *- FL      |
| 5   | 1   |          | *BOOT LID INNER TRIM COVER  | Serviceable  | 349.30 FL  | *- FL      |
| 6   | 2   |          | *BOOT LID LAMP              | Dented       | 564.60 FL  | *564.60 FL |
| 7   | 1   |          | *BOOT LID LOGO              | Necessary    | 52.20 FL   | *52.20 FL  |
| 8   | 1   |          | *BOOT LID COROLLA EMBLEM    | Necessary    | 42.40 FL   | *42.40 FL  |
| 9   | 1   |          | *BOOT LID ALTIS EMBLEM      | Necessary    | 44.20 FL   | *44.20 FL  |
| 10  | 2   |          | *TAILLAMP                   | Dented / Cut | 726.20 FL  | *726.20 FL |
| 11  | 2   |          | *TAILLAMP LOWER BRACKET     | Cracked      | 145.40 FL  | *145.40 FL |
| 12  | 1   |          | *REAR END PANEL             | Bent         | 581.20 FL  | *581.20 FL |
| 13  | 1   |          | *END PANEL TOP GARNISH      | Buckled      | 229.40 FL  | *229.40 FL |
| 14  | 1   |          | *SPARE TYRE PANEL           | Repair       | 876.30 FL  | *- FL      |
| 15  | 1   |          | *SPARE TYRE BOARD COVER     | Serviceable  | 284.20 FL  | *- FL      |
| 16  | 1   |          | *SPARE TYRE NUT & SCREW     | Serviceable  | 49.90 FL   | *- FL      |
| 17  | 1   |          | *REAR BUMPER FASCIA         | Bent         | 482.20 FL  | *482.20 FL |
| 18  | 2   |          | *REAR BUMPER SIDE RETAINER  | Distorted    | 258.60 FL  | *258.60 FL |
| 19  | 2   |          | *REAR BUMPER BRACKET        | Bent         | 104.40 FL  | *104.40 FL |
| 20  | 1   |          | *REAR BUMPER REINFORCEMENT  | Bent         | 420.20 FL  | *420.20 FL |
| 21  | 1   |          | *REAR BUMPER REVERSE SENSOR | Dented       | 300.00 FS  | *200.00 FS |
| 22  | 1   |          | *REAR BUMPER CLIP           | Necessary    | 40.00 FS   | *40.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                   |          |          |
|---------------------------------------------------|----------|----------|
| Sub Total (\$)                                    | 6,967.60 | 5,110.70 |
| - List Item Discount on L Items 25.00/25.00% (\$) | 1,625.70 | 1,196.88 |
| Total Parts (\$)                                  | 5,341.90 | 3,913.82 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                            | Particulars                                                                                      | Lab.Type | Repairer's      | Amount          |
|-------------------------------|--------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>           |                                                                                                  |          |                 |                 |
| 1                             | TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET                               | New      | 120.00          | 60.00           |
| 2                             | TO APPLY UNDERSEALING                                                                            | New      | 80.00           | 60.00           |
| 3                             | TO PUTTY AND SPRAY REPLACED PARTS                                                                | New      | 1,000.00        | 800.00          |
| 4                             | TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS | New      | 900.00          | 700.00          |
| <b>Gross Labour Cost (\$)</b> |                                                                                                  |          | <b>2,100.00</b> | <b>1,620.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >