

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	07:14HRS
ACCIDENT DATE	10-Feb-22
BUS CAPTAIN NAME	MUHAMMAD ASHARI BIN ABD SAMAD
THIRD PARTY CLAIM AGAINST	United Overseas Insurance Ltd

BUS REGISTRATION NUMBER	SMB3008U
BUS TYPE (SD/DD)	SD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1 : MATERIALS, PARTS & CONSUMABLE ITEMS

NO.	Part or Item Description	Quantity	Total Cost
1	OS FRONT VIEW MIRROR ASSY / BR	1	\$ 751.90
2	REFLECTOR STICKER / M	2	\$ 40.00
		7% GST	\$ 55.43
		PARTS TOTAL COST	\$ 847.33

751.90
-10%
712.71

SECTION 2 : LABOUR COST - ASSESSMENT / REPAIR / SPRAY PAINT

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE ITEMS NOS. 1-2	\$ 650.00
	7% GST
	\$ 45.50
	LABOUR TOTAL COST
	\$ 695.50

SPRAY PAINTING \$640 PER PANEL
LABOUR CHARGES \$650 PER DAY

Total - 1012.71

SECTION 3 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

1 day
m m
p/p
by day

BUS TYPE (SD / DD)	SD
--------------------	----

DATE IN	
DATE & TIME SURVEY	
DATE OUT	
TOTAL NUMBER OF DAYS	
LOSS OF USE COST	\$ 300.00

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Steve (LKK)
23/2/22 12:22pm

SUMMARY	
SECTION NO.	COST
1	\$ 847.33
2	\$ 695.50
3	\$ 300.00
TOTAL	\$ 1,842.83