

# ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	07:14HRS
ACCIDENT DATE	10-Feb-22
BUS CAPTAIN NAME	MUHAMMAD ASHARI BIN ABD SAMAD
THIRD PARTY CLAIM AGAINST	United Overseas Insurance Ltd

BUS REGISTRATION NUMBER	SMB3008U
BUS TYPE (SD/DD)	SD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

## SECTION 1 : MATERIALS, PARTS & CONSUMABLE ITEMS

NO.	Part or Item Description	Quantity	Total Cost
1	OS FRONT VIEW MIRROR ASSY	1	\$ 751.90
2	REFLECTOR STICKER	2	\$ 40.00
		7% GST	\$ 55.43
		<b>PARTS TOTAL COST</b>	\$ 847.33

## SECTION 2 : LABOUR COST - ASSESSMENT / REPAIR / SPRAY PAINT

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE ITEMS NOS. 1-2	\$ 650.00
SPRAY PAINTING \$640 PER PANEL LABOUR CHARGES \$650 PER DAY	7% GST \$ 45.50
	<b>LABOUR TOTAL COST</b> \$ 695.50

## SECTION 3 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

		DATE IN	
		DATE & TIME SURVEY	
		DATE OUT	
		TOTAL NUMBER OF DAYS	
BUS TYPE (SD / DD)	SD		
	LOSS OF USE COST	\$	300.00

SUMMARY	
SECTION NO.	COST
1	\$ 847.33
2	\$ 695.50
3	\$ 300.00
<b>TOTAL</b>	\$ 1,842.83