

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Vel No

SMV 7220

Tuesday

Wednesday

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0126/2022/JT
DATE : 21-Feb-22
WIP : 12516

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ANG SENG PING
ADDRESS : 21 COMPASSVAL ROAD
#10-22
SINGAPORE 544754
TELEPHONE : HP +65 96213523
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100476375
VEHICLE NO : **SLE 729 M**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 26/7/2016
ENGINE NO : CZC 540632
CHASSIS NO : WAUZZZ8V7G1090069
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Feb-22
PLACE OF ACCIDENT : SLIP ROAD BETWEEN ANG MO KIO AVE 5
AND YIO CHU KANG ROAD

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLE 729 M

SURVEYOR'S RECOMMENDATIONS	ACCIDENT NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	UBI ROAD 1		
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	500 ✓
4	TO RESPRAY FRONT BUMPER.	\$ 900.00	550 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 3,202.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408669

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAIB@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 729 M

ESTIMATED LABOUR CHARGES FOR

PRICES

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rehd</i>	1	\$ 2,377.00	✓ 1901.60
2	FRONT BUMPER FIXING PARTS <i>see</i>	1	\$ 195.00	+
3	FRONT BUMPER TRIM COVER - LH / RH <i>see</i>	2	\$ 364.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>MT</i>	1	\$ 175.00	X
5	FRONT BUMPER PULL STRAP - LOWER <i>see</i>	4	\$ 231.00	X
6	FRONT BUMPER GUIDE SECTION - LH / RH <i>not see</i>	2	\$ 86.00	X
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>LH missing</i>	2	\$ 244.00	122 97.20
8	RADIATOR GRILLE <i>could</i>	1	\$ 765.00	✓ 612
9	RADIATOR GRILLE UPPER COVER <i>not ? nn</i>	1	\$ 109.00	✓ ? X
10	CAUTION STICKER <i>see</i>	1	\$ 16.00	✓ 12.40
11	AIR COND STICKER <i>see</i>	1	\$ 9.00	✓ 6.64
12	FRONT BUMPER REINFORCEMENT BEAM <i>? nn</i>	1	\$ 847.00	✓ X 122.80
13	FRONT BUMPER FOAM FILLER PIECE <i>could</i>	1	\$ 154.00	✓ } S.S.
14	FRONT BUMPER REINFORCEMENT BEAM COVER <i>could</i>	1	\$ 63.00	✓ } 49.84
15	HORN - LH / RH <i>see</i>	2	\$ 426.00	+
16	FRONT WHEEL HOUSING LINER - LH <i>see</i>	1	\$ 183.00	+
17	HEADLIGHT - LH / RH <i>see</i>	2	\$ 5,620.00	+
18	LIFT CYLINDER - LH / RH <i>see</i>	2	\$ 422.00	+
19	LIFT CYLINDER HOSE <i>see</i>	1	\$ 204.00	+
20	RADIATOR AIR GUIDE - LH / RH <i>? nn</i>	2	\$ 56.00	✓ X
SUB TOTAL SPARE PARTS			\$ 12,546.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Adrian
Resurveyed
S.S.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6641 1183

EMAIL: NORA@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 729 M

MATERIAL LIST FOR ACCIDENT VEHICLE

ITEM & PRICES

DAMAGED PARTS & PRICES

ITEM	S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21		RADIATOR SEAL - RH OUTER	1	\$ 9.00	X
22		RADIATOR AIR GUIDE - UPPER CENTER	1	\$ 14.00	X
23		BONNET CATCH HOOK	1	\$ 71.00	X
24		FRONT NO PLATE	S/N	\$ 60.00	60
25		SUNDRIES		\$ 300.00	X

TOTAL SPARE PARTS	:	\$ 13,000.00
TOTAL LABOUR CHARGES	:	\$ 3,202.00
GRAND TOTAL	:	\$ 16,202.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Adrian Lim

28/02/22

Not Authorised, 03 Days

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT