

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS

WORKSHOP : UBI ROAD 1

CONTACT NO : 6366 2323

FAX NO : 6841 1183

REFERENCE : PA/OD/0106/2022/JT

DATE : 15-Feb-22

WIP : 11759

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : SENG KOK ANN, IVAN
ADDRESS : BLK 455B ANG MO KIO STREET 44
#18-15
SINGAPORE 567455
TELEPHONE : HP +65 90681101
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800152116-02
VEHICLE NO : **SKU 8789 P**
MODEL CODE : AUDI A3 SB 1.0 TFSI
MODEL YEAR : 28/12/2018
ENGINE NO : CHZ B21941
CHASSIS NO : WAUZZZ8V1KA010998
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Feb-22
PLACE OF ACCIDENT : SLIP ROAD EXITING FROM CTE TOWARDS
MOULMEIN ROAD

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKU 8789 P

SURVEYOR'S RECOMMENDATIONS	S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1		TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2		TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X
3		TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,450.00	1000 ✓
4		TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER.	\$ 3,000.00	1100 ✓
5		TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES			: \$ 6,352.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKU 8789 P

ESTIMATED LABOUR CHARGES FOR

REMARKS S/NETT PARTS DESCRIPTION QTY S/NETT REMARKS

1	FRONT BUMPER	Pyis	1	\$	2,146.00	*
2	FRONT BUMPER FIXING PARTS		1	\$	195.00	x
3	FRONT BUMPER GUIDE SECTION - LH / RH	xla	2	\$	86.00	f
4	FRONT BUMPER GRILLE - CENTER	xla	1	\$	179.00	t
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	xla	1	\$	332.00	t
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	xla	2	\$	636.00	x
7	RADIATOR GRILLE	Cracked	1	\$	1,406.00	✓ 1124.80
8	RADIATOR GRILLE CLOSING ELEMENT	? cracked	1	\$	210.00	? 168
9	FRONT BUMPER AIR GUIDE GRILLE - LH	xla	1	\$	210.00	x
10	FRONT BUMPER FOAM FILLER PIECE	? nn	1	\$	211.00	? X
11	FRONT BUMPER REINFORCEMENT BEAM	? nn	1	\$	847.00	? X
12	FRONT BUMPER REINFORCEMENT BEAM COVER	? nn	1	\$	136.00	? X
13	AIR COND STICKER		1	\$	9.00	✓ 6.64
14	CAUTION STICKER		1	\$	16.00	✓ 12.40
15	HORN - LH	xla xla	1	\$	213.00	x
16	BONNET	Dented	1	\$	3,370.00	✓ 2696
17	BONNET ATTACHMENT PARTS	xla	1	\$	172.00	x
18	BONNET EDGE PROTECTION	xla	1	\$	31.00	✓ 24.72
19	BONNET STRIKER - LH		1	\$	123.00	x
20	BONNET MICRO-SWITCH - LH	xla	1	\$	228.00	x

SUB TOTAL SPARE PARTS : \$ 10,756.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

AD 1, SINGAPORE 55, UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKU 8789 PD

S/N	PARTS DESCRIPTION	QTY	RES/NETT	SPARE	REMARKS
-----	-------------------	-----	----------	-------	---------

21	BONNET BOWDEN CABLE - CENTER	1	\$	64.00	X
22	BONNET RELEASE CABLE COVER	1	\$	11.00	X
23	BONNET CATCH HOOK - LOWER	1	\$	71.00	X
24	BONNET CATCH HOOK - UPPER	1	\$	100.00	X
25	FRONT WHEEL HOUSING LINER - LH	1	\$	183.00	X
26	HEADLIGHT - LH	1	\$	5,455.00	X
27	LIFT CYLINDER - LH	1	\$	156.00	X
28	LIFT CYLINDER HOSE	1	\$	78.00	X
29	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$	21.00	? X
30	RADIATOR AIR GUIDE - LH / RH	2	\$	56.00	? X
31	RADIATOR SEAL - RH OUTER	1	\$	9.00	? X
32	RADIATOR AIR GUIDE - UPPER CENTER	1	\$	14.00	X
33	FRONT NO PLATE	S/N	\$	100.00	✓ 100
34	SUNDRIES		\$	300.00	? X

TOTAL SPARE PARTS	:	\$	17,374.00
TOTAL LABOUR CHARGES	:	\$	10,756.00
GRAND TOTAL	:	\$	28,130.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

DAMAGED PARTS & PRICES

Adnan
22/02/22

Not Authorized, 04 Days

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: