



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22001729/Uvf3e2 Date: 17/03/2022 Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJQ 8788A	Veh. Inspected	SMP 3608P
	Policy No.		Coverage (\$)	0.00
	Claim No.	2022 22003948SL	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	23/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	LEXUS ES250 (A)	c.c	2494
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JTHBJ1GG702091141	Colour	WHITE
	Odometer	107499 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	PIRELLI	7 mm
	L/H Front Tyre	215/55 R17	PIRELLI	7 mm
	R/H Rear Tyre	215/55 R17	PIRELLI	7 mm
	L/H Rear Tyre	215/55 R17	PIRELLI	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	10/02/2022	Inspection Date	23/02/2022
	Survey held at	TAN LIM MOTOR PTE LTD NO.1 DEFU LANE 6 SINGAPORE 539365		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	