

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC
 Mr Lau Liang Peng, Daniel
 38 Chay Yan Street
 #19-05

Singapore 169907

Closed by : Richmond Ho
 Svc Consultant :
 Remarks : Mr Lau Liang Peng, D

Inv.No. . : B&P
 Inv.date. : 21/02/2022
 WIP No. . : 13936
 Veh.In/Out: 19/02/2022
 *Tel.No. . : Mobile: 96820475
 Reg.No. . : SMU1635Y
 Reg.date . : 30/07/2020
 Mileage .. : 0
 Chassis No: YV1XZACADL2207486

GST Reg.No: M28920628X
 0 Page 1

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BONNET, FRT BUMPER, FRT GRILL, FRT LH HEADLAMP, FRT LH FENDER, INNER PANEL, LH DOOR, LH WHEEL ARCH, TOP PANEL, ETC	0	7650.00	0		7,650.00	S 5100 ✓
800	TO PUTTY SPRAY PAINT ON FRT BONNET, FRT BUMPER, FRT LH FENDER, FRT LH INNER PANEL, FRT LH DOOR, LH A PILLAR, LH CHASSIS, ETC	0	6000.00	0		6,000.00	S 4875 ✓
802	TO VACCUM & TOP UP A/C GAS	0	350.00	0		350.00	S ✓
802	TO REPLACE FRONT WINDSCREEN	0	850.00	0		850.00	S ✓
287	TO REPLACE FRONT DASHBOARD, LH & RH AIR BAG, KNEE AIR BAG, ETC	0	5760.00	0		5,760.00	S 4370 ✓
287	TO REPLACE ALL SEAT BELTS, SRS CONTROL MODULES INCLUDE PROGRAMMING, ETC	0	4320.00	0		4,320.00	S 2880 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T 6430 4700 www.wearnes.com

Co reg no. 199501400R / GST reg no. M28920628X

Steve (LKK) 24/2/22 12M
 OD-MNL
 EXC-1-?
 PIP
 MRLY
 17 Lys

- C00001

SERVICE ESTIMATE

SL: SERVICE SALES - PC

Mr Lau Liang Peng, Daniel
38 Chay Yan Street
#19-05

Singapore 169907

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 21/02/2022

WIP No. . : 13936

Veh.In/Out: 19/02/2022

*Tel.No. . : Mobile: 96820475

Reg.No. . : SMU1635Y

Reg.date . : 30/07/2020

Mileage . : 0

Chassis No: YV1XZACADL2207486

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Lau Liang Peng, D

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
031	TO REPLACE FRONT LH RIM	0		50.00	0		50.00	S ✓
10	COMPUTERISED WHEEL ALIGNMENT	0		280.00	0		280.00	S ✓
89994	TO INSTALL FRONT WINDSCREEN FI	0		280.00	0		280.00	S ✓
280	TO FOCUS HEADLAMP	0		180.00	0		180.00	S ✓
287	TO CHECK WIRING INCLUDE	0		540.00	0		540.00	S ✓
RESETTING OF ALL ELECTRICAL								
MODULES								
	BUMPER COVER FRT XC4	1.0	EA	2199.70			2,199.70	S ✓ 1979.73
	RADIATOR GRILLE XC40	1.0	EA	1012.60			1,012.60	S ✓ 911.34
	BUMPER CARRIER FRT L	1.0	EA	30.50			30.50	S ✓ 27.45
	BUMPER CARRIER FRT R	1.0	EA	30.50			30.50	S ✓
	V032136051/BUMPER UN	1.0	EA	177.80			177.80	S ✓ 160.02
	BUMPER FOAM FRT ALL	1.0	EA	286.90			286.90	S ✓ 258.21
	BUMPER SPOILER FRT A	1.0	EA	562.20			562.20	S ✓ 505.98
	BUMPER GRILLE LOWER	1.0	EA	152.30			152.30	S ✓
	PROTECTING PLATE FRT	1.0	EA	742.90			742.90	S ✓ 668.61
	FOG COVER BRACKET LH	1.0	EA	59.30			59.30	S ✓ 53.37

- C00001 SERVICE ESTIMATE

SL: SERVICE SALES - PC
Mr Lau Liang Peng, Daniel
38 Chay Yan Street
#19-05

Singapore 169907

Closed by : Richmond Ho
Svc Consultant :
Remarks : Mr Lau Liang Peng, D

Inv.No. . : B&P 0 Page 3
Inv.date. : 21/02/2022
WIP No. . : 13936
Veh.In/Out: 19/02/2022
*Tel.No. . : Mobile: 96820475
Reg.No. . : SMU1635Y
Reg.date . : 30/07/2020
Mileage .. : 0
Chassis No: YV1XZACADL2207486

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	FOG COVER BRACKET RH X <i>nn</i>	1.0 EA	59.30			59.30 S	
	FOG COVER LH XC40 18 <i>mis</i>	1.0 EA	80.40			80.40 S	72.36
	FOG COVER RH XC40 18 X <i>nn</i>	1.0 EA	80.40			80.40 S	
	NUMBER PLATE RETAINE X <i>nn</i>	1.0 EA	70.50			70.50 S	
	EXPANDING NUT XC40 1 <i>ne</i> 2 <i>10-8</i>	10.0 EA	6.30			63.00 S	11.34
	BUMPER BRACKET FRT L <i>ne</i>	1.0 EA	90.90			90.90 S	81.81
	BUMPER BRACKET FRT R <i>BR</i>	1.0 EA	90.90			90.90 S	81.81
	BUMPER CLIP S80 07- <i>ne</i>	10.0 EA	5.70			57.00 S	51.30
	BUMPER INSTALLING MT <i>ne</i>	1.0 EA	96.50			96.50 S	86.85
	WIPER GRILLE CLIP XC <i>ne</i> ne	10.0 EA	8.30	ne		83.00 S	74.70
	BLIND RIVET 4.0*21 P <i>ne</i>	10.0 EA	4.70			47.00 S	42.30
	BUMPER CLIP 8x8,5 <i>ne</i>	10.0 EA	7.80			78.00 S	70.20
	WIDENER FRT LH XC40 <i>mis</i>	1.0 EA	193.20			193.20 S	173.88
	WHEELARCH FRT LH XC4 <i>BR</i>	1.0 EA	240.90			240.90 S	216.81
	AIR DEFLECTOR LH XC4 <i>mis</i>	1.0 EA	77.30			77.30 S	69.57
	PROTECTION LH <i>ne</i> X <i>nn</i>	1.0 EA	68.20			68.20 S	
	BONNET FRT XC40 18- <i>nn</i>	1.0 EA	2580.50			2,580.50 S	2322.45

- C00001
 Mr Lau Liang Peng, Daniel
 38 Chay Yan Street
 #19-05

Singapore 169907

Closed by : Richmond Ho
 Svc Consultant :
 Remarks : Mr Lau Liang Peng, D

SERVICE ESTIMATE

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 4
 Inv.date. : 21/02/2022
 WIP No. . : 13936
 Veh.In/Out: 19/02/2022
 *Tel.No. . : Mobile: 96820475
 Reg.No. . : SMU1635Y
 Reg.date . : 30/07/2020
 Mileage .. : 0
 Chassis No: YV1XZACADL2207486

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	V031356752/BONNET HI	1.0 EA	318.10			318.10 S	286.29
	V031356753/BONNET HI	1.0 EA	318.10			318.10 S	286.29
	BONNET STRUT XC40 18	1.0 EA	250.00			250.00 S	
	SAFETY CATCH XC40 18	1.0 EA	179.60			179.60 S	
	BONNET LOCK LH XC40	1.0 EA	218.10			218.10 S	196.29
	BONNET LOCK RH XC40	1.0 EA	218.10			218.10 S	
	WIRE BOX REAR	1.0 EA	129.50			129.50 S	
	BONNET CABLE XC40 21	1.0 EA	129.50			129.50 S	
	TRIM COVER FENDER LH	1.0 EA	159.10			159.10 S	143.19
	CLIP	10.0 EA	5.90			59.00 S	53.10
	FENDER PANEL FRT LH	1.0 EA	1364.70			1,364.70 S	1228.23
	FENDER CARRIER BRACK	1.0 EA	30.50			30.50 S	27.45
	V032234761/FENDER CA	1.0 EA	173.40			173.40 S	156.06
	V032297849/BUMPER RA	1.0 EA	1481.20			1,481.20 S	1333.08
	BRACKET BUMPER BEAM	1.0 EA	168.20			168.20 S	151.38
	BRACKET BUMPER BEAM	1.0 EA	168.20			168.20 S	151.38
	BRACKET BEAM FRT XC4	1.0 EA	102.30			102.30 S	92.07

- C00001 **SERVICE ESTIMATE**

SL: SERVICE SALES - PC
Mr Lau Liang Peng, Daniel
38 Chay Yan Street
#19-05

Singapore 169907

Closed by : Richmond Ho
Svc Consultant :
Remarks : Mr Lau Liang Peng, D

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 5
Inv.date. : 21/02/2022
WIP No. . : 13936
Veh.In/Out: 19/02/2022
*Tel.No. . : Mobile: 96820475
Reg.No. . : SMU1635Y
Reg.date . : 30/07/2020
Mileage ... : 0
Chassis No: YV1XZACADL2207486

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	FLANGE SCREW M12x40	2.0 EA	4.50			9.00 S	8.10
	HEADLAMP LED LH XC40	1.0 EA	2260.60			2,260.60 S	2034.54
	HEADLAMP CONTROL UNI	1.0 EA	577.40			577.40 S	
	S HCM RELOAD XC40	1.0 EA	105.70			105.70 S	95.13
	PARK SENSOR FRT/REAR	4.0 EA	205.20			820.80 S	184.68
	CABLE HARNESS LH XC4	1.0 EA	1743.40			1,743.40 S	
	PARK CABLE HARNESS F	1.0 EA	140.40			140.40 S	126.36
	ALLOY RIM 18 5-spoke	1.0 EA	1363.80			1,363.80 S	1227.42
	KNUCKLE ARM LH XC40	1.0 EA	889.10			889.10 S	
	V032221265/HUB KIT F	1.0 EA	548.70			548.70 S	
	CONTROL ARM LOWER LH	1.0 EA	327.20			327.20 S	
	FLANGE SCREW M12x75	1.0 EA	5.90			5.90 S	
	FLANGE SCREW M12x60	1.0 EA	5.90			5.90 S	
	SEMS SCREW M14x105	1.0 EA	9.50			9.50 S	
	SEMS SCREW M14x80	1.0 EA	5.90			5.90 S	
	SUBFRAME FRT XC40 18	1.0 EA	2343.00			2,343.00 S	
	CROSS MEMBER FRT XC4	1.0 EA	259.30			259.30 S	

- C00001

SERVICE ESTIMATE

Mr Lau Liang Peng, Daniel
38 Chay Yan Street
#19-05

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Singapore 169907

Inv.No. . : B&P 0 Page 6

Inv.date. : 21/02/2022

WIP No. . : 13936

Veh.In/Out: 19/02/2022

*Tel.No. . : Mobile: 96820475

Reg.No. . : SMU1635Y

Reg.date . : 30/07/2020

Mileage . : 0

Chassis No: YV1XZACADL2207486

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Lau Liang Peng, D

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	STAY LH CROSSMEMBER 1 2 X nn	1.0 EA	27.90			27.90	S
	STAY RH CROSSMEMBER 1 2 X nn	1.0 EA	27.90			27.90	S
	V036011625/STEERING 1 2 X nn	1.0 EA	2346.40			2,346.40	S.
	S PSCM RELOAD XC40 1 2 X nn	1.0 EA	109.90			109.90	S
	ABSORBER MTG FRT XC4 1 2 X nn	1.0 EA	123.00			123.00	S
	BEARING ABSORBER XC4 1 2 X nn	1.0 EA	123.00			123.00	S
	BUMP STOP XC40 18- 1 2 X nn	1.0 EA	64.90			64.90	S
	PROTECTING BELLOWS 1 2 X nn	1.0 EA	18.30			18.30	S
	ABSORBER FRT LH XC40 1 2 X nn	1.0 EA	392.10			392.10	S
	V032221271/LINK ROD 1 2 X nn	2.0 EA	159.70			319.40	S
	CMP SENSOR FRT LH XC 1 2 X nn	1.0 EA	315.10			315.10	S
	ABS SENSOR FRT/REAR 1 2 X nn	1.0 EA	224.60			224.60	S
	DASHBOARD XC40 18- 1 BR	1.0 EA	2076.40			2,076.40	S / 1868.76
	CONTROL UNIT SRS XC4 1 BR	1.0 EA	2103.70			2,103.70	S / 1893.33
	S SRS RELOAD XC40 1 BR	1.0 EA	152.20			152.20	S / 136.98
	E AIRBAG MODULE ST 1 BR	1.0 EA	2998.80			2,998.80	S / 2698.92
	E AIRBAG MODULE pa 1 BR	1.0 EA	3180.50			3,180.50	S / 2862.45

SERVICE ESTIMATE

- C00001

SL: SERVICE SALES - PC

Mr Lau Liang Peng, Daniel
38 Chay Yan Street
#19-05

Singapore 169907

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 7

Inv.date. : 21/02/2022

WIP No. . : 13936

Veh.In/Out: 19/02/2022

*Tel.No. . : Mobile: 96820475

Reg.No. . : SMU1635Y

Reg.date . : 30/07/2020

Mileage . : 0

Chassis No: YV1XZACADL2207486

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Lau Liang Peng, D

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	E AIRBAG MODULE KN	1.0 EA	2362.60			2,362.60 S	2126.34
	SENSOR AIRBAG FRT S6	2.0 EA	431.70			863.40 S	777.06
	E SEAT BELT FRT LH	1.0 EA	1363.10			1,363.10 S	1226.79
	V031462121/*E* SEAT	1.0 EA	1458.60			1,458.60 S	1312.74
	E SEAT BELT REAR L	2.0 EA	1394.90			2,789.80 S	2510.82
	E SEAT BELT REAR C	1.0 EA	1394.90			1,394.90 S	1255.41
	IU STICKER	1.0 EA	6.30			6.30 S	5.67
	WINDSCREEN FRT ALL X	1.0 EA	1740.60			1,740.60 S	1566.54
	D PRIMER GLASS & P	1.0 EA	43.30			43.30 S	38.97
	D GLASS CLEANER H	1.0 EA	82.40			82.40 S	74.16
	D WINDSCREEN SEALA	2.0 EA	164.40			328.80 S	295.92
	V031652847/RAIN SENS	1.0 EA	384.50			384.50 S	346.05
	A PILLAR CLIP White	10.0 EA	18.30			183.00 S	164.70
	A PILLAR CLIP PINK S	2.0 EA	12.80			25.60 S	23.04
	FENDER FOAMBLOCK LH	1.0 EA	101.60			101.60 S	91.44
	V031651852/PANEL INS	1.0 EA	50.00			50.00 S	45
	SIDE PANEL FRT LH XC	1.0 EA	170.50			170.50 S	

- C00001

Mr Lau Liang Peng, Daniel
38 Chay Yan Street
#19-05

Singapore 169907

SERVICE ESTIMATE

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 8

Inv.date. : 21/02/2022

WIP No. . : 13936

Veh.In/Out: 19/02/2022

*Tel.No. . : Mobile: 96820475

Reg.No. . : SMU1635Y

Reg.date . : 30/07/2020

Mileage .. : 0

Chassis No: YV1XZACADL2207486

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Lau Liang Peng, D

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	SIDE PANEL BRACKET L	1.0 EA	159.10			159.10 S	143.19
	SIDE PANEL BRACKET L	1.0 EA	65.70			65.70 S	59.13
	V032234760/FRONT SEC	1.0 EA	224.50			224.50 S	202.05
	SIDE PANEL CATCH XC4	1.0 EA	143.20			143.20 S	

Labour Total 26,260.00
Parts Total 54,740.50
Package Total 0.00

Gross Total. 81,000.50

Net..... 81,000.50

GST @ 7.0% 5,670.04

Total..... 86,670.55

Paid..... 0.00

Please Pay.. 86,670.55

GST: S=StdRated; O=OutOfScope; Z=ZeroRated