

## COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC7133T

Make : HYUNDAI

Model : I-40

Date: 21/02/2022

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	ROCKER PANEL OUTER GARNISH RH			<i>ann</i> \$732.80
1	FRT FENDER RH			<i>bt</i> \$663.00
1	FRT FENDER SHIELD RH			<i>nn x</i> \$174.90
1	FRT WHEEL HUB CAP RH			<i>act</i> \$217.20
	SUB TOTAL		<i>1613</i>	\$1,787.90
	LESS 20%			\$357.58
	DISCOUNTED TOTAL		<i>1290.40</i>	\$1,430.32
	<i>Supp</i> Put down City Lab Logo Sticker RH new \$75 net		<i>75</i>	
				\$-
	Labour Charge			
	PANEL BEATING			<i>\$60</i> \$900.00
	SPRAY PAINTING CHARGE			<i>\$50</i> \$750.00
	TUFF KOTE			<i>30</i> \$60.00
	WIRING CHARGE		<i>1240</i>	<i>nn x</i> \$60.00
	TOTAL LABOUR			\$1,770.00
	ESTIMATE TOTAL		<i>2605.40</i>	
			<i>45 \$2100</i>	\$3,200.32
			<i>2 days #</i>	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*Tamplin 97495749*  
*WP' 2/2/22 @ 440*  
*2/3 hours after repair*  
*tamplin@lkkauto.com*  
*2-3 days*

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company