

ASS. REC. BY:

REF:

TJ / 22 001 7361ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

8 49,366 1/2

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S14D 5881A

Yr Regn:

11, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Tag Priv

c.c

1798

Colour

MP White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

343930

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B3K4 10.30 75271

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Pirelli

Front

Rear

R/Bal.

6

mm

R/Bal.

7

mm

L/Bal.

6

mm

L/Bal.

7

mm

D.O.A.

21/2/22

D.O.I.

23/2/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Got BZ, awaiting BV.

Max @ 24,750k

1/4 11 Sep @ 19,300k Cash

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Fees:

Others:

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5881A

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

23 FEB 2022

Not Authored AAD2202-

C1 Imp 819,300/h

SHD5881A

JTDKB3FU103075271

200303878K

TOYOTA

PRIUS

21/02/2022

SHB2081L/III

01/11/2018

PART

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 FILLER, REAR BUMPER EXTENSION, LH
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 BOARD ASSY, BACK DOOR TRIM
- 1 WEATHERSTRIP, BACK DOOR
- 1 BOARD, BACK DOOR TRIM
- 1 LENS & BODY, REAR COMBINATION LAMP, LH (UPPER)
- 1 LENS AND BODY, REAR LAMP, LH (LOWER)
- 1 BOX, DECK FLOOR, RH
- 1 BOX, DECK FLOOR, LH
- 1 BOARD, REAR FLOOR, NO.1
- 1 BOX, DECK FLOOR, REAR
- 1 PANEL ASSY, DECK TRIM SIDE, LH
- 1 COVER, FLOOR UNDER, NO.1 LH
- 1 COVER, FLOOR UNDER, NO.2 RH
- 1 COVER, REAR FLOOR CTR
- 1 COVER, DECK TRIM, REAR
- 1 PAN, REAR FLOOR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH

LIST

\$	B ₁	442.60	✓
\$	B ₁	332.70	✓
\$	nc	15.40	✓
\$	B ₁	576.30	✓
\$	Dis	116.50	✓
\$	Sm	117.70	X
\$	Sm	123.70	X
\$	mt cm	123.70	✓
\$	B ₁	1,147.80	✓
\$	cm	925.60	✓
\$	Dis	259.20	✓
\$	Dis/nc	372.30	✓
\$	Sm	225.20	X
\$	cm	443.30	✓
\$	cm	502.00	✓
\$	Sm	313.60	X
\$	Sm	313.00	X
\$	Sm	519.00	X
\$	nc	105.80	X
\$	Sm	355.90	X
\$	mt	175.10	✓
\$	mt	241.90	✓
\$	mt	229.90	✓
\$	nc Sm	126.70	X
\$	R	583.40	X
\$	B ₁	650.30	✓
\$	nc	467.00	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2202-**SHD5881A**

- 1 SWITCH ASSY, BACK DOOR OPENER
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 DUCT ASSY, QUARTER VENT, LH
- 1 SPOILER, SUB ASSY, REAR
- 1 GLASS, BACK WINDOW FIX
- 1 MOULDING, BACK WINDOW, LOWER NO.2
- 1 MOULDING, BACK WINDOW, OUTSIDE LH NO.2
- 1 MOULDING, BACK WINDOW, OUTSIDE RH NO.2
- 1 DAM, BACK DOOR GLASS ADHESIVE, NO.2
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH
- 1 REAR TAILGATE TOYOTA LOGO
- 1 REAR TAILGATE WORDING 'PRIUS'
- 1 REAR TAILGATE WORDING 'HYBRID'
- 1 COVER, FRONT BUMPER
- 1 BRACKET, FRONT BUMPER EXTENSION MOUNTING
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 REINFORCEMENT, FRONT BUMPER, NO.2
- 1 ABSORBER, FRONT BUMPER, LOWER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 EXTENSION, FRONT BUMPER, RH
- 1 EXTENSION, FRONT BUMPER, LH
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 UNIT ASSY, HEADLAMP, LH
- 1 UNIT ASSY, HEADLAMP, RH
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 EMBLEM ASSY, RADIATOR GRILLE
- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH
- 1 EMBLEM, SIDE PANEL
- 1 FENDER SUB-ASSY, FRONT LH
- 1 LINER, FRONT FENDER, LH

\$	1m	179.10	X
\$	1m	88.50	X
\$	1m	67.00	X
\$	1m	1,575.40	X
\$	phatent	761.40	✓
\$	1m	23.60	—
\$	1m	30.90	—
\$	1m	30.90	—
\$	1m	28.90	—
\$	1m	242.50	X
\$	1m	242.50	X
\$	1m	61.00	X
\$	1m	61.00	X
\$	1m	47.90	—
\$	1m	54.60	—
\$	1m	54.60	—
\$	1m	516.00	✓
\$	1m	103.40	X
\$	1m	716.60	X
\$	1m	246.10	X
\$	CMF	132.70	✓
\$	1m	79.60	X
\$	1m	80.10	X
\$	1m	82.30	X
\$	1m	120.10	X
\$	1m	120.10	X
\$	1m	29.30	✓
\$	1m	2,637.60	—
\$	1m	2,637.60	—
\$	CMF	346.00	—
\$	1m	170.10	X
\$	1m	90.80	—
\$	1m	977.80	X
\$	1m	206.70	X
\$	1m	54.60	X
\$	1m	977.80	✓
\$	1m	202.50	X

Trans-cab Auto Services Pte Ltd**AAD2202-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5881A

- 1 EMBLEM, SIDE PANEL
- 1 SUPPORT, RADIATOR, UPPER RH
- 1 SUPPORT, RADIATOR, UPPER LH
- 1 SUPPORT SUB-ASSY, RADIATOR, UPPER
- 1 SUPPORT SUB-ASSY, RADIATOR, LOWER
- 1 SUPPORT SUB-ASSY, RADIATOR, LH
- 1 SUPPORT SUB-ASSY, RADIATOR, RH
- 1 HOOD SUB-ASSY
- 1 HINGE ASSY, HOOD, LH
- 1 HINGE ASSY, HOOD, RH
- 1 BRACE, HOOD LOCK SUPPORT
- 1 INSULATOR, HOOD
- 1 LOCK ASSY, HOOD
- 1 SEAL, HOOD TO FRONT END PANEL
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 CONDENSER ASSY, COOLER
- 1 CLEANER ASSY, AIR
- 1 BRACKET, HEADLAMP, LH
- 1 BRACKET, HEADLAMP, RH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 COVER, RADIATOR SUPPORT OPENING

\$	<i>Nu</i>	54.60	✓
\$	<i>Bu</i>	78.90	—
\$	<i>Bu</i>	78.90	—
\$	<i>Pu</i>	377.10	✓
\$	<i>Ry</i>	409.90	✓
\$	<i>Di</i>	245.10	✓
\$	<i>Di</i>	245.10	✓
\$	<i>Ry</i>	983.10	✓
\$	<i>Di</i>	58.90	—
\$	<i>Di</i>	58.90	—
\$	<i>Di</i>	78.30	✓
\$	<i>Return</i>	410.90	✓
\$	<i>Di</i>	135.00	✓
\$	<i>Pu</i>	51.60	X
\$	<i>Sm</i>	219.10	X
\$	<i>Bi</i>	1,783.20	✓
\$	<i>Pu</i>	1,147.00	X
\$	<i>R</i>	34.80	X
\$	<i>R</i>	34.80	X
\$	<i>R</i>	59.30	X
\$	<i>R</i>	59.30	X
\$	<i>Di</i>	235.30	✓
TOTAL	\$	30,722.30	
25%	\$	7,680.58	
	\$	23,041.73	

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR TAILGATE STICKER "Trans-Cab"
- 1 REAR TAILGATE STICKER "6555-3333"
- 1 REAR BUMPER PROTECTOR
- 2 SEAM SEALANT
- 1SET REAR BUMPER RETAINER CLIP

\$	<i>Red</i>	700.00	2205m
\$	<i>Mer</i>	95.00	65m
\$	<i>Mer</i>	150.00	80m
\$	<i>Mer</i>	200.00	✓
\$	<i>Mer</i>	130.00	30m
\$	<i>Mer</i>	80.00	30m
\$	<i>Mer</i>	80.00	30m
\$	<i>Mer</i>	180.00	50m
\$	<i>Sm</i>	250.00	X
\$	<i>Mer</i>	85.00	X

Trans-cab Auto Services Pte Ltd**AAD2202-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5881A

- 1 REAR NUMBER PLATE WITH HOLDER
- 1SET TAILLAMP LOWER CLIP
- 1SET TAILLAMP UPPER CLIP
- 1 END PANEL TRIM CLIP
- 1 REAR SPOILER CLIP
- 1SET BUMPER CLIP FRT
- 1 FRONT NUMBER PLATE WITH MOULDING
- 1SET CLIP, FRONT FENDER LINER
- 1SET FRNT BUMPER RETAINER CLIP
- 1 HOOD INSULATOR CLIP

\$	<i>Del</i> 140.00	<i>455m</i>
\$	<i>nn</i> 55.00	—
\$	<i>nn</i> 55.00	—
\$	<i>nn</i> 65.00	—
\$	<i>nn</i> 70.00	X
\$	<i>nn</i> 95.00	<i>655m</i>
\$	<i>Del</i> 200.00	<i>455m</i>
\$	<i>nn</i> 85.00	X
\$	<i>nn</i> 85.00	X
\$	<i>nn</i> 55.00	—
TOTAL \$	2,855.00	

TOTAL PARTS \$ 25,896.73**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ 300.00 *1801*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *801*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 *1801*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *Repair* 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ 180.00 *601*

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ *nn* 480.00 X

To transfer of Fender fittings, attachments and perform water seepage test.

\$ *nn* 480.00 X

Trans-cab Auto Services Pte Ltd**AAD2202-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5881A

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$ 380.00 100/

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ nn 380.00 X

To check steering geometry and computer wheel alignment

\$ nn 220.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 250.00 120/

Towing Fees

\$ 150.00 50/

Putty And Spray Painting Of The Affected Portion.

\$ 2,200.00 1920/

To reinstall rear bumper parking sensor.

\$ 170.00 50/

To Check Electrical Lighting Concerned.

\$ 170.00 40/

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ nn 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ nn 220.00 X

To replace, refix and top up coolant for radiator

\$ 170.00 50/

To lift-up / out engine with gear box and refit.

\$ nn 440.00 X

To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.

\$ nn 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ nn 380.00 X

TOTAL \$ 10,290.00**Over All Total \$ 36,186.73**

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5881A

AAD2202-

(PART-BY-PART) Repair Days

25 DAYS

14 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 878K

Vehicle Details

Vehicle No.: SHD5881A

Vehicle to be Exported: Yes

Intended Deregistration Date: 22 Feb 2022

Vehicle Make: TOYOTA

Vehicle Model: PRIUS SDR HATCHBACK (AUTO)

Primary Colour: Red

Manufacturing Year: 2018

Engine No.: 2ZR2B61358

Chassis No.: JTDKB3FU103075271

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$26,605.00

Original Registration Date: 01 Nov 2018

First Registration Date: 01 Nov 2018

Transfer Count: 0

Actual ARF Paid: \$14,247.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 31 Oct 2026

PARF Rebate Amount: \$10,685.00

Intended COE Rebate Details

COE Expiry Date: 31 Oct 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$23,736.00

COE Rebate Amount: \$13,917.00

Total Rebate Amount: \$24,602.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Feb 2022

OK