

# BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

## Repair Estimate

Vehicle number: SFS5778K

Make & Model: Toyota Corolla Altis

Chassis number: MR053REH104523609

| 2015 |                                       |      |                        |
|------|---------------------------------------|------|------------------------|
| No.  | Description of spare parts            | Qty  | Amount                 |
| 1    | Front bumper                          | 1    | \$ <del>581.45</del>   |
| 2    | Front bumper clips                    | 1set | \$ <del>60.00</del>    |
| 3    | Front bumper RH side retainer         | 1    | \$ <del>432.10</del>   |
| 4    | RH headlamp assy                      | 1    | \$ <del>861.00</del>   |
| 5    | RH front fender                       | 1    | \$ <del>656.00</del>   |
| 6    | RH front fender emblem                | 1    | \$ <del>54.00</del>    |
| 7    | RH front fender splash shield         | 1    | \$ 200.90              |
| 8    | RH front fender splash shield clips   | 1set | \$ 55.00               |
| 9    | RH front sport rim (original)         | 1    | \$ 1,644.00            |
| 10   | RH front lower arm                    | 1    | \$ <del>602.70</del>   |
| 11   | RH front knuckle arm                  | 1    | \$ 521.20              |
| 12   | RH front shock absorber               | 1    | \$ <del>398.10</del>   |
| 13   | RH front wheel bearing                | 1    | \$ <del>95.70</del>    |
| 14   | RH front tie rod end                  | 1    | \$ 93.20               |
| 15   | RH side mirror <del>assy</del> convex | 1    | \$ 108.60 1,257.70     |
| 16   | RH front door                         | 1    | \$ <del>1,079.60</del> |
| 17   | RH front door frame black sticker     | 1    | \$ 59.60 75.00         |
| 18   | RH front door rubber weatherstrip     | 1    | \$ 148.00 191.70       |
| 19   | RH front door inner trim board        | 1    | \$ <del>903.00</del>   |
| 20   | RH front door inner trim board clips  | 1set | \$ <del>60.00</del>    |
| 21   | RH rear door                          | 1    | \$ 1,112.10 1,211.70   |
| 22   | RH rear door frame black sticker      | 1    | \$ 59.60 75.00         |
| 23   | RH rear door rubber weatherstrip      | 1    | \$ 148.00 191.70       |
| 24   | RH rear door inner trim board         | 1    | \$ 672.00 903.00       |
| 25   | RH rear door inner trim board clips   | 1set | \$ 30.00 60.00         |
| 26   | RH rear sport rim (original)          | 1    | \$ 945.85 1,644.00     |
| 27   | RH rear wheel bearing                 | 1    | \$ 450.00 654.10       |
| 28   | RH rear shock absorber                | 1    | \$ 296.40              |
| 29   | RH rear axle beam                     | 1    | \$ <del>2,466.20</del> |
| 30   | Rear windscreen glass rubber moulding | 1    | \$ 60.80               |
| 31   | RH rear fender                        | 1    | \$ 845.10 986.30       |
| 32   | Rear bumper                           | 1    | \$ 540.20              |

|    |                              |          |                             |
|----|------------------------------|----------|-----------------------------|
| 33 | Rear bumper clips            | 1set     | \$ <del>30.00</del> 60.00   |
| 34 | Rear bumper RH side retainer | 1        | \$ <del>109.30</del> 132.10 |
| 35 | LH taillamp                  | 1        | \$ <del>316.80</del>        |
|    |                              |          |                             |
|    |                              | Total    | \$ 19,120.65                |
|    |                              | Less 25% | \$ 4,780.16                 |
|    |                              | Total    | \$ 14,340.49                |

NEC  
NECV  
NECV x nn

| No. | Special Nett Items              | Qty    | Amount                    |
|-----|---------------------------------|--------|---------------------------|
| 1   | RH front tyre                   | 1      | \$ <del>380.00</del>      |
| 2   | RH rear tyre                    | 1      | \$ <del>380.00</del>      |
| 3   | Brake fluid                     | 1      | \$ <del>60.00</del>       |
| 4   | Rear windscreen glas sealant    | 1      | \$ <del>30.00</del> 70.00 |
| 5   | Rear windscreen glas inner seal | 1      | \$ <del>20.00</del> 50.00 |
|     |                                 |        |                           |
|     |                                 |        |                           |
|     |                                 | Total: | \$ 940.00                 |

NNA

NECV

|    | Labour and painting                                                                                                                            | Amount                        |
|----|------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|
| 1  | Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas | \$ <del>1000.00</del> 1600.00 |
| 2  | Spray painting on affected areas and panels                                                                                                    | \$ <del>800.00</del> 1,300.00 |
| 3  | Check wiring and lighting system                                                                                                               | \$ <del>60.00</del>           |
| 4  | Apply rust coating chemical on affected areas and panels                                                                                       | \$ <del>80.00</del>           |
| 5  | Refocus and adjust headlamps assy                                                                                                              | \$ <del>60.00</del>           |
| 6  | Remove and replace front undercarriage parts to assist repair                                                                                  | \$ <del>350.00</del>          |
| 7  | Remove and replace RH front door inner mechansim to new door                                                                                   | \$ 120.00                     |
| 8  | Remove and replace RH rear door inner mechansim to new door                                                                                    | \$ 120.00                     |
| 9  | Remove and replace rear undercarriage parts to assist repair                                                                                   | \$ <del>450.00</del>          |
| 10 | Remove and reinstall rear bumper reverse sensors to assist repair                                                                              | \$ <del>60.00</del> 100.00    |
| 11 | Test drive and adjust wheel alignment system                                                                                                   | \$ <del>100.00</del>          |
| 12 | Remove and reinstall rear windscreen glass to assist repair                                                                                    | \$ <del>120.00</del> 200.00   |

NDX

NDX

NNX

**BIFROST AUTO PTE LTD**

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

**Parts price revised and Supplementary**

Vehicle number: SFS5778K

Make & Model: Toyota Corolla Altis

| No. | Description of spare parts               | Qty          | Amount           |
|-----|------------------------------------------|--------------|------------------|
| 1   | RH front door outer handle               | 1            | \$ 157.25        |
| 2   | RH front door outer handle rubber gasket | 1            | \$ 12.00         |
| 3   | RH rear door outer handle                | 1            | \$ 157.25        |
| 4   | RH rear door outer handle rubber gasket  | 1            | \$ 12.00         |
|     |                                          |              |                  |
|     |                                          | Total        | \$ 338.50        |
|     |                                          | Less 25%     | \$ 84.63         |
|     |                                          | <b>Total</b> | <b>\$ 253.88</b> |

UTV ✓  
NEC ✓  
UTV ✓  
UTV ✓

| No. | Description of spare parts (Special Nett) | Qty | Amount |
|-----|-------------------------------------------|-----|--------|
|     |                                           |     |        |
|     |                                           |     |        |
|     |                                           |     |        |
|     |                                           |     |        |
|     |                                           |     |        |
|     |                                           |     |        |

| No. | Labour                | Amount               |
|-----|-----------------------|----------------------|
| 1   | Labour                | \$ <del>350.00</del> |
| 2   | Spray painting bonnet | \$ <del>250.00</del> |
|     |                       |                      |
|     |                       |                      |
|     |                       |                      |
|     |                       |                      |
|     |                       |                      |
|     |                       |                      |
|     |                       |                      |
|     |                       |                      |

} NNX

Total Amount

\$

853.88

Resurvey

18/3/2022

1330 hrs

Tommi Mui

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

|    |                                                                                 |  |                      |
|----|---------------------------------------------------------------------------------|--|----------------------|
| 13 | Remove and reinstall roof lining, seats, seat belts and carpet to assist repair |  | \$ <del>350.00</del> |
|    |                                                                                 |  |                      |

NNX

Total: \$ 4,890.00

Survey + Resurvey

25/2/2022

TG in

11/11

1430 hrs

Lump sum repair

Repair days 7

Spare Parts: \$ 14,340.49

Special Nett: \$ 940.00

Labour: \$ 4,890.00

Total Amount: \$ 20,170.49 21,024.37

Parts 5052.94

SN 50.00

Labour 1980.00

7082.94

@ 20% 1416.59

5666.35

LS 5650/r

TG in 11/11

1/4/2022

L&K Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: