

NS/INC22001747/Tgy3

ASS. REC. BY: Taufik

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. MT/1165387-003

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Awang

Vehicle: IN / OUT

Veh No: SHC30464 Yr Regn: 2019, Apr /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai / Lorry C.C. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 261320 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH C851CVH 41746

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wanphat

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 21/2/22Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh finalised LS \$1100, 3 days. (Red \$3864.30, 78%)

Date/Time, File Pass to?

☐ : Preli. Report1) 22/03 Typist☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: TPLump Sum / ~~1100~~ 1100Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

REPAIR ESTIMATE*

VEHICLE NO SHC3046M

DATE 21.02.2022

MAKE/REG

02/04/19

MODEL : HYUNDAI IONIQ G2

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR DOOR PANEL RH			\$1,789.90
1	REAR DOOR MOULDING RH			\$125.30
1	REAR FENDER RH			\$1,768.30
	SUB TOTAL			\$3,683.50
	LESS 20%			\$736.70
	DISCOUNTED TOTAL			\$2,946.80
1	REAR FENDER RH ADVERTISEMENT			\$100.00
1	REAR DOOR ADVERTISEMENT			\$100.00
1	DOOR COMFORT APP			\$75.00
				\$267.50
	Labour Charge			
	Panel Beating			\$900.00
	Spray Painting Charge			\$700.00
	Remove/refix upholstery			\$90.00
	Check Wiring			\$60.00
	TOTAL LABOUR			\$1,750.00
	ESTIMATE TOTAL			\$4,964.30
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanpin 974157 reg
wp' 21/2/22 E Spr
1/1 rising after repair
temporarily/shortly
2-3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by repairer


Signature:

Date:

Date/Time: 21.02.2022 15:48 Page : 1

Team: ARC Repair TP(CLSO)1 JOB CARD Sales Order: 4176392 JC NO305506049

CUSTOMER	REG NO.: SHC3046M	MILEAGE
VMS COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL E.....1/2.....F
STOMER NO. 7010045	MODEL: IONIQ(G2)	DATE/TIME IN 21.02.2022 13:45
DRESS 383 SIN MING DRIVE	YR OF MANU. 02.04.2019	TARGET DATE
Singapore SINGAPORE 575717	CHASSIS CODE KMHC851CVKU141746	COMPLETION DATE/TIME:
65508755 (R) (O) (P)		
COUNT CARD NO.		

JOB DESCRIPTION	
Accident Date: 21.02.2022	
NATURE: 3P 21.02.2022	
3/NO	LABOR CODE
DESCRIPTION	
	

ECKED & PASSED OUT BY:	
SERVICE ADVISOR	CUSTOMER'S SIGNATURE

Acknowledgement Slip	Exit Pass
Vehicle No.: SHC3046M CHIANG	Vehicle No.: SHC3046M
Signature/Date	Name of Service Advisor
of Service Advisor	Date
returned to Service Reception upon collection	To be kept by Security Guard