

**RE: Accident involving GBF2849A & XD8579P at 47 jalan buroh on 13.02.2022/0840**

From: apexi HKS (apexih@yahoo.com.sg)

To: cynthia.ang@income.com.sg

Date: Thursday, 17 February 2022, 09:34 am SGT

Dear Cynthia ,

Pls advise on the liability issue.

Regards  
Chai  
85498387

Sent from Yahoo Mail on Android

On Fri, Feb 11, 2022 at 2:30 PM, apexi HKS  
<apexih@yahoo.com.sg> wrote:

Dear Cynthia ,

We have confirmed finalize amount of \$5850 for the repair cost .

Please advise on the liability and we shall proceed with our LOD.

Thank you

Regards  
Chai  
85498387

Sent from Yahoo Mail on Android

On Mon, Jan 17, 2022 at 10:36 AM, MTSurvey  
<MTSurvey@income.com.sg> wrote:

Classification: *Restricted*

HI

Yes

**Lim Chan Heng**

Claims Executive  
Operations, Motor & Personal Lines

T: +65 62026532

 **income**  
made yours

**From:** apexi HKS <apexih@yahoo.com.sg>

**Sent:** Monday, 17 January 2022 10:34 AM

**To:** MTSurvey <MTSurvey@income.com.sg>; MTSurvey <MTSurvey@income.com.sg>

**Subject:** RE: Accident involving GBF2849A & XD8579P at 47 jalan buruh on 13.02.2022/0840

Dear Mr Lim,

The insured company for XD8579P is it NTUC ?

Please advise.

Regards

Allan

Sent from Yahoo Mail on Android

On Mon, Jan 17, 2022 at 10:23 AM, MTSurvey  
<MTSurvey@income.com.sg> wrote:

Classification: *Restricted*

Dear Workshop,

Thank you for your email.

The Survey/ appointment has been scheduled on 18/01/2022.

While we will do our best to survey the damage on site, there may be a situation that we would need your co-operation to assist us to do it remotely via video. Our surveyor will liaise with you accordingly.

Please ensure that the vehicle and the repair estimate are available. We seek your understanding and patience that our surveyor will survey the vehicle at the earliest possible time.

For future survey request, may we request you to provide the following information in the format below.

Survey Type : (New Survey / Resurvey)	
Vehicle to be surveyed :	
Income Insured Vehicle :	
Date of Accident :	
Date of Survey :	
Name of Workshop :	
Address of Survey Location :	
Name of Contact Person :	
Contact Number :	

Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 13 Jan 2022 / 11:52:22

Receipt Date/Time : 13 Jan 2022 / 11:52:21

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-220113-001338

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - XD8579P As at 13 Jan 2022/10:00:00 Insurance Co: NTUC INCOME INS CO-OP LTD			
1	Insurance Enquiry - XD8579P Enquiry Fee 20220113115124143674	7.00	0.49	7.49
	<b>Sub-Total</b>	7.00	0.49	7.49
	<b>Total Before Rounding</b>	7.00	0.49	7.49
	<b>Rounding Difference</b>			0.04
	<b>Total Amount Payable</b>			7.45
	<b>Paid By</b>			
	421808XXXXXX7506	eNETS Credit Card		7.45
	<b>Total</b>			7.45
	<b>Cash Change</b>			0.00
	<b>Tendered Amount</b>			7.45
	<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



068811  
21  
Fax:  
om.sg  
Number: 199903512M  
axa.com.sg



## CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) ■ Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 ■ Road Transport Act, 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VSX/P2454917 Account No. : 04437  
Coverage : Third Party Only  
Sum Insured : NIL  
Name of Policy Holder : HENG LIM SERVICES PTE LTD  
Vehicle Registration No. : XD8579P  
Period of Insurance : From 15/09/2021 To 14/09/2022 (Both Dates Inclusive)

### PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE\*

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

### LIMITATIONS AS TO USE\*

- (a) Use in connection with the Policyholder's business
- (b) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business
- (c) Use for social, domestic and pleasure purposes

This Policy does not cover

- (a) Use for hire or reward or for racing, pace-making, reliability trial or speed-testing
- (b) Use whilst drawing a greater number of trailers in all than is permitted by Law

(06)

### EXCESS :

Sect II-Any Authorised Driver : SGD 3,000.00  
(For Unnamed Driver Excess, please refer to your policy)

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGOMEZHA on 13/10/2021

### IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

# RESPRAY AUTOMOTIVE PTE LTD

8, KAKI BUKIT AVE 4, #04-06, PREMIER @KB, (415875)

Reg : 202106720W

Tel: 82632225

Email: tfyong1966@gmail.com

Not Authorized  
to sell  
merch

HP 90096608  
Tel: 62563561  
Zhang Huiyao  
4 days.

Vehicle Number : GBF2849A  
Vehicle Model : TOYOTA HIACE  
Accident Date : 13.01.2022  
Original Reg Date : 25.08.2016

Date : 13.01.2022  
Chassis : KDH2010193905  
TP Ins. NTUC

1/5 #5850

## ESTIMATE

1	1 pc	Front bonnet	R		985.20	X
2	2 pc	Front bonnet hinges	17	78.90	157.80	X
3	1 pc	Front bonnet inner lock	52		298.50	X
4	1 pc	Front corner panel RH	321		285.60	✓
5	1 pc	Front Bumper	D.S		598.20	✓
6	1 pc	Front Bumper towing cover	M.S	30	49.80	✓
7	1 pc	Front Bumper grille base	C ne		558.90	✓ 479.10
8	1 set	Front Bumper grille clips	1er		30.00	✓
9	1 pc	Front Bumper lower grille	C ne		245.80	✓
10	1 pc	Front Bumper upper grille	C ne		385.90	✓
11	2 pcs	Front Bumper Side Retainers	O/S C ne	145/30	140.10 290.60	✓ 12C
12	1 pc	Front Bumper Reinforcement	321		458.20	✓
13	1 set	Front Bumper Clips	1er		50.00	✓
14	1 pc	Front Bumper Top Beam	17		379.80	X
15	2 pcs	Front Bumper Reinforcement Side Bracket	17	138.00	276.00	X
16	2 pc	Front Bumper Lower Side cover	O/S 70.1	95.80	191.60	✓ 12C
17	2 pc	Front Bumper foglamp	O/S C ne	326.40	652.80	✓ 12C
18	2 pc	Front Bumper foglamp covers	O/S 70.1	98.50	197.00	✓ 12C
19	2 pc	Headlamps LED	O/S C ne	3,066.80	6,133.60	✓ 12C 2420.8
20	2 set	Headlamps clips	17	30.00	60.00	X
21	1 pc	Air Con Condenser	17		1,521.90	X
22	1 pc	Condenser Air Con Pipe	17		310.60	X
23	1 pc	Condenser Suction Pipe	17		526.80	X
24	1 pc	Condenser Discharge Pipe	17		437.60	X
25	1 pc	Front washer tank	17		158.20	X
26	1 pc	Front wiper garnish	17		245.80	X
27	1 pc	Front wiper garnish rubber seal	17		86.30	X
28	1 pc	Radiator	17		1,856.90	X
29	1 pc	Radiator spare tank	17		205.80	X
30	1 pc	Radiator brace panel	R		298.20	X
31	1 pc	Front support panel	R		425.90	X
32	1 pc	Front door RH	AD 121		1,458.90	✓
33	1 pc	Front door weatherstrip RH	1er		198.50	✓
34	1 pc	Front door innertrim RH	17		528.10	X



35	1 set	Front door innertrim RH clips	17		30.00	X
36	1 pc	Front door checker RH	11		78.50	X
37	2 pc	Front door hinges RH	7W1	95.60	191.20	X
38	1 pc	Front door innerlock RH	17		385.60	X
39	1 pc	Front door step garnish RH	70m		245.90	X
40	1 pc	Front door wirehardness RH	R		485.90	X
41	1 pc	Front side mirror RH	17		685.20	X
42	1 pc	Front brake booster pump	17		1,859.60	X
43	1 pc	Front brake fluid pipe	17		258.90	X
44	1 pc	Front brake fluid tank	17		485.20	X
45	1 pc	Turbo Intercooler	17		1,856.30	X
46	1 pc	Turbo intercooler cover	17		385.90	X

subtotal 27,493.00  
 Less 25% 6,873.25  
 total 20,619.75

### Special Nett

1	1 pc	Front Number Plate with casing	50.00	50.00	40
2	1 pc	Front door company sticker	30.00	30.00	✓
3	1 set	Front support panel sealant	60.00	60.00	X

### Labour charge

Panel Beating, to weld and align damaged parts	2,000.00	600
Spray painting	2,000.00	800
Check Wiring on headlamp	150.00	20
Anti rust	120.00	30
Remove and install condenser /top up gas	17 100.00	X
Check diagnostic of vehicle management /control unit	17 180.00	X
Repair and realign chassis member	17 200.00	X

Total 25,509.75

I, the Auto Centre, hereby acknowledge the Repairs as follows:

- To survey and estimate spray painting
- To do the required repair work
- Parts and materials are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repsitor

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

P-7738-60  
 25%  
 P-5803.95  
 SN-70  
 L-1450  
 7323.95  
 20%  
 5819.