

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	---

Attn: Douglas Ong Chu Chong

Date: 29 Jun 2022

**Preliminary Advice**

Insured	: SLM2144U		
Vehicle No			
TP Vehicle No	: SJB3666E	Accident Date	: 18/02/2022
Make	: HONDA ODYSSEY HYBRID ABSOLUTE	Assignment Date	: 23/02/2022
Date of Inspection	: 24/02/2022	Est. Duration of Repair	: 4
Inspection At	: CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,016.72
Revised Amount	:S\$	3,628.00
Check Items (Estimated)	:S\$	2,026.72
Total	:S\$	5,654.72

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
-------------------	------	--

Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- (   ) The vehicle is economical for repair
- (   ) The vehicle is not economical for repair
- (   ) Part-by-Part repair
- (   ) Lump Sum repair
  
- ( X ) The above survey was conducted on a 'without prejudice' basis.  
Please note that the preliminary advice amount (Revised & Check Items)  
stated are subject to consistency check, part prices and labour cost.