

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG: 200707743D GST REG: 200707743D

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before alterations or repairs
- Any damaged part(s) during resurvey
- Parts or repairs need confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Dependable item(s) must be resurveyed and
- is subject to approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

23-Feb-22

## ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1647 L

1 pc	Front bumper	\$ 430.90	/cat
1 pc	Front bumper centre grille cover - Upper	\$ 108.50	/sur
1 pc	Front bumper emblem "HYUNDAI"	\$ 28.00	/nec
1 pc	Front bumper o/s side upper bracket	\$ 12.00	/nec
2 pcs	Front bumper o/s & n/s side retainer @ \$39.30	\$ 78.60	/nec
2 pcs	Front bumper n/s & o/s fog lamp @ \$642.50	\$ 1,285.00	X SUC
2 pcs	Front bumper n/s & o/s fog lamp moulding @ \$93.00	\$ 186.00	/sur
2 pcs	Front n/s & o/s headlamp @ \$1198.80	\$ 2,397.60	X
1 pc	Front o/s fender	\$ 490.70	Xr
1 pc	Front o/s fender inner shield	\$ 114.70	1 /cat
1 pc	Front n/s & o/s fender garnish- Delta @ \$15.30	\$ 15.30	X SUC
1 pc	Front n/s fender emblem "Blue-drive"	\$ 26.20	/nec
1 pc	Front o/s wheel cover	\$ 116.00	X SUC
		\$ 5,289.50	
Less 20%		\$ 1,057.90	
		\$ 4,231.60	

### S/NETT

1 pc	Front bumper clips	\$ 48.00	24
1 set	Front o/s fender inner shield clips	\$ 28.00	14
	Sundry	\$ 50.00	XNW
	Towing fee	\$ 50.00	/
	To adjust & focus front head lamps	\$ 80.00	40
	To check for front o/s wheel alignment	\$ 80.00	60
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same.	\$ 800.00	360
	To putty and spray painting on front bumper, front o/s fender, bonnet, front n/s fender	\$ 900.00	360
	To apply rustproofing on the repaired and replaced panels.	\$ 80.00	30
		\$ 6,347.60	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Theruan  
82235769

26/0-56

24/2/22 1500

Plp 4days w/p