



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
-		Ref:	CS/TP22001766/Evy3n2
LEIGHTONASIA YONGNAM JOINT VENTURE 2A WINSTEDT DRIVE #01-02 SINGAPORE 228001- -		Date:	11/03/2022
		Code:	TP2
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.		Veh. Inspected	SGG 7979K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	24/02/2022
2. Vehicle Particulars & Condition			
Make & Model	BMW M135	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	WBA7L120507H18661	Colour	WHITE
Odometer	8093 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	BRIDGESTONE	4 mm
L/H Front Tyre	225/40 R18	BRIDGESTONE	4 mm
R/H Rear Tyre	225/40 R18	BRIDGESTONE	4 mm
L/H Rear Tyre	225/40 R18	BRIDGESTONE	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/02/2022	Inspection Date	24/02/2022
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	