



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21011346/Tvf3e2-1	
			Date: 08/03/2022	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 6405X	Veh. Inspected	GBK 5850Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	21/21/21/VC00/025124	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	23/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA 150	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JTFAT35YX0K215330	Colour	SILVER	
Odometer	56928 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	155 R12 (D)	BRIDGESTONE	6/6 mm	
L/H Rear Tyre	155 R12 (D)	BRIDGESTONE	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/11/2021	Inspection Date	15/11/2021	
Survey held at	JL AUTO SERVICES PTE LTD BLK 3006 UBI ROAD 1 #01-346 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	