

ESTIMATE  
T&C AUTOMOTIVE

1 KAKI BUKIT AVENUE 6 #01-68 AUTOBAY@KAKI BUKIT SINGAPORE 417883

CONTACT PERSON: AH CHAI

CONTACT NUMBER: 9007 5148

WAUZZZ8TOBA 009985

TP Chuan, TP MS16

Hui Rong

|                 |          |                |         |
|-----------------|----------|----------------|---------|
| Vehicle Number: | SMQ2183Z | Vehicle Model: | AUDI S5 |
|-----------------|----------|----------------|---------|

| No    | List Of Items                                   | Amount SGD                           |
|-------|-------------------------------------------------|--------------------------------------|
| 1     | Front Bonnet <i>Repl</i>                        | \$ 2,249.00 <i>x</i>                 |
| 2     | Front Bonnet Insulator <i>3 new</i>             | \$ 288.00 <i>x</i>                   |
| 3     | Front Bonnet Catch Hook                         | \$ 135.00 <i>x</i>                   |
| 4     | Front Bonnet Edge Protection x 2 <i>3 new</i>   | \$ 68.00 <i>x</i>                    |
| 5     | Front Bonnet Lid Lock with Micro Switch         | \$ 288.00 <i>x</i>                   |
| 6     | Front Bumper <i>Distorted</i>                   | \$ 2,138.00 <i>✓</i>                 |
| 7     | Front Bumper Reinforcement <i>Not new</i>       | \$ 880.00 <i>x</i>                   |
| 8     | Front Bumper Support x 2 <i>RT cracked</i>      | \$ <del>88.00</del> 44.00 <i>✓</i>   |
| 9     | Front Bumper Fog Lamp RHS <i>cracked</i>        | \$ 299.80 <i>✓</i>                   |
| 10    | Front Bumper Fog Lamp Cover RHS <i>Missing</i>  | \$ 168.50 <i>✓</i>                   |
| 11    | Front Bumper Nozzle Cover <i>Missing</i>        | \$ 120.00 <i>✓</i>                   |
| 12    | Front Bumper Tow Cover <i>Not new</i>           | \$ 48.00 <i>x</i>                    |
| 13    | Front Bumper Sensor x 2 <i>1 piece damaged</i>  | \$ <del>440.00</del> 220.00 <i>✓</i> |
| 14    | Front Bumper Sensor Holder x 4 <i>new</i>       | \$ 80.00 <i>✓</i>                    |
| 15    | Front Grille 'QUATTRO' <i>cracked</i>           | \$ <del>2,240.00</del> 1680 <i>✓</i> |
| 16    | Front Grille Logo <i>3 new</i>                  | \$ 128.00 <i>✓</i>                   |
| 17    | Front Grille 'S5' Emblem                        | \$ 118.00 <i>✓</i>                   |
| 18    | Front Support Panel <i>cracked</i>              | \$ 1,127.00 <i>✓</i>                 |
| 19    | Oil Cooler <i>Not new</i>                       | \$ 829.00 <i>x</i>                   |
| 20    | Aircon Condensor <i>Not new</i>                 | \$ 1,320.00 <i>x</i>                 |
| 21    | Secondary Air Pump <i>cracked</i>               | \$ 1,047.90 <i>✓</i>                 |
| 22    | Secondary Air Pump Upper Hose <i>3 new</i>      | \$ 199.80 <i>x</i>                   |
| 23    | Secondary Air Pump Lower Hose                   | \$ 199.80 <i>x</i>                   |
| 24    | Front Headlamp RHS <i>cracked</i>               | \$ 2,578.10 <i>✓</i>                 |
| 25    | Front Headlamp Lower Bracket RHS <i>Not new</i> | \$ 198.00 <i>x</i>                   |
| 26    | Front Headlamp Nozzle <i>cracked</i>            | \$ 220.00 <i>✓</i>                   |
| 27    | Front Fender RHS <i>Dented</i>                  | \$ 980.00 <i>✓</i>                   |
| 28    | Front Fender Inner Shield <i>torn</i>           | \$ <del>260.00</del> 193 <i>✓</i>    |
| TOTAL |                                                 | \$ 18,435.80                         |

11144.20  
Len 10%: 10029.78

Special Nett Items

|                    |                                               |                                    |
|--------------------|-----------------------------------------------|------------------------------------|
| 1                  | Bonnet Insulator Clip Set <i>Not new</i>      | \$ 60.00 <i>x</i>                  |
| 2                  | Bumper Clip Set <i>new</i>                    | \$ <del>60.00</del> 30.00 <i>✓</i> |
| 3                  | Front Number Plate with Holder <i>Not new</i> | \$ 60.00 <i>x</i>                  |
| 4                  | Fender Inner Shield Clip Set <i>new</i>       | \$ <del>60.00</del> 30.00 <i>✓</i> |
| 5                  | Radiator Coolant <i>Not new</i>               | \$ 100.00 <i>x</i>                 |
| TOTAL SPECIAL NETT |                                               | \$ 340.00                          |

60

Vehicle Number:

SMQ2183Z

Vehicle Model:

AUDI S5

## Labour Charges

|              |                                                                        |    |          |       |
|--------------|------------------------------------------------------------------------|----|----------|-------|
| 1            | Towing service                                                         | \$ | 150.00   | X     |
| 2            | To check wiring and lighting                                           | \$ | 80.00    | 30    |
| 3            | To remove, replace and refix front bumper sensor                       | \$ | 100.00   | 50    |
| 4            | To remove and refix radiator assy                                      | \$ | 150.00   | X     |
| 5            | To remove, refix and top up aircon gas                                 | \$ | 150.00   | X 160 |
| 6            | To apply anti-rust proofing on affected areas                          | \$ | 100.00   | 30    |
| 7            | To perform diagnostic check for fault codes and reset factory settings | \$ | 250.00   | X 100 |
| 8            | To panel beat and replace damaged parts on affected areas              | \$ | 1,800.00 | 80    |
| 9            | To putty and spray paintings on affected areas                         | \$ | 1,800.00 | 600   |
| TOTAL LABOUR |                                                                        | \$ | 4,580.00 |       |

ESTIMATE PARTS AND LABOURS GRAND TOTAL

\$ 23,355.80

total 11899.78

H/S: 9.51c

06 Days.

9.51c.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: