

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No. 199007	/198R GST Reg. No. 19	1-96U <i>1</i> I	90-K	
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef:	CS/AGI22001775/Utf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	06/05/2022	
			Co	ode:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLU 3196X	Veh. Inspected		SMU 6474L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10014004 /KY	Excess (\$)		0.00	
	Assign From	SHAFAWATI	Assign Date		24/02/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA VIOS 1.5 E (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	MR2B23F3201200242	Colour		BLUE	
	Odometer	19811 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/50 R16	MICHELIN		7 mm	
	L/H Front Tyre	195/50 R16	MICHELIN		7 mm	
	R/H Rear Tyre	195/50 R16	MICHELIN		7 mm	
	L/H Rear Tyre	195/50 R16	MICHELIN		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	22/02/2022	Inspection Date		24/02/2022	
	Survey held at	FASTECH AUTO PTE LTD	•			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	1-/	Estimate Days of Repair				

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: