



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Ref: CS/EQI22001776/Evf3n2 Date: 28/03/2022 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBK 8356P	Veh. Inspected	SJE 19C
Policy No.		Coverage (\$)	0.00
Claim No.	DM22HO00276/MT	Excess (\$)	0.00
Assign From	MELODY TEOH	Assign Date	24/02/2022
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ CLA180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD1173422N246847	Colour	BLACK
Odometer	48942 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	BRIDGESTONE	5 mm
L/H Front Tyre	225/40 R18	BRIDGESTONE	5 mm
R/H Rear Tyre	225/40 R18	BRIDGESTONE	5 mm
L/H Rear Tyre	225/40 R18	BRIDGESTONE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/02/2022	Inspection Date	08/03/2022
Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	