



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJE19C

EQ INSURANCE COMPANY LIMITED

MOTOR CLAIM DEPARTMENT
5 MAXWELL ROAD #17-00
TOWER BLOCK, MND COMPLEX
SINGAPORE 069110
62239433

Vehicle & Document Information

WIP No 55177
Reg No/Reg Date SJE19C / 27/08/2015
Date In/Mileage / 0
Chassis No WDD1173422N246847
Engine No 27091030721540
Make/Model MB/CLA 180 (C117) "URBAN"
Colour/Trim 021 191 Cosmos Blac/ 041 151-Leather Twi

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WE000058	Credit	22/02/2022/ 17:48	K0	301 / Kerlyn Ong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request
M BPNSUN
POLICY NO/ACC DATE : 2100426457-06 // 22/02/2022
DRIVE IN/EXCESS : 22/02/2022 // GBK8356P - EQ
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES
RESPRAY FRONT BUMPER & RH/ FRONT FENDER

A BPILAB
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT

A BPILAB
TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT

M FRONT BUMPER	1.00	1431.91	00.00	1431.91
M FRONT BUMPER COMPANY SIGN	1.00	63.99	00.00	63.99
M SPACER RING	1.00	6.97	00.00	6.97
M RH/ FRONT BUMPER LOWER GRILLE	1.00	49.10	00.00	49.10
M RH/ HEADLAMP	1.00	2646.06	00.00	2646.06

960 / 1920.00

800 / 1800.00

0.10 380.00

120.00

Steve (LKK)

8/3/22, 11.30am

W PL

PIP

M PL M

Kerlyn Ong Kai Li
DID : 6771 4420 HP : 9186 5113
Email : kerlyn.ong@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Confirmed & accepted by

3 dys

Nett 8,418.03
7% GST on 8418.03 589.26

Total Payable 9,007.29

LKK Auto Consultants hence notify
the Repairer of the following:

To resurvey before/after spray painting

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Acknowledged by Repairer

Signature:

Date:

and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg