



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
 WORKSHOP : UBI ROAD 1
 CONTACT NO : 6366 2323
 FAX NO : 6841 1183
 REFERENCE : PA/OD/0129/2022/JT
 DATE : 21-Feb-22
 WIP : 12570

xiao Chen.
25 Days H/S
\$ 95683.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 Attn: Motor Claims Dept
 Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR SHANKAR S/O NAGANAMBALAGARAN
 ADDRESS : BLK 107 SPOTTISWOODE PARK ROAD
 #21-118
 SINGAPORE 080107
 TELEPHONE : HP +65 96743561
 TYPE OF CLAIM : OWN DAMAGE CLAIM
 POLICY NO : 7210032966
 VEHICLE NO : **SMY 9247 X**
 MODEL CODE : AUDI A6 SEDAN 2.0 TFSI S
 MODEL YEAR : 30/3/2021
 ENGINE NO : DKY 015277
 CHASSIS NO : WAUZZZF23MN054487
 MILEAGE : -
 DATE IN : -
 ESTIMATED BY : JOHNNY BOO / ALLAN WU
 ACCIDENT DATE : 19-Feb-22
 PLACE OF ACCIDENT : AYE TOWARDS KEPPEL



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 9247 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250 ✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,700.00	✓✓
4	TO CARRY OUT PRESSURISE, VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	? ✓ <i>sl.s.</i>
5	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,800.00	? X
6	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER.	S/N \$ 800.00	✓✓
SUB TOTAL LABOUR CHARGES		: \$ 7,380.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 9247 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO SETUP THE VEHICLE CAR O-LINER TO FACILITATE THE REPAIR.	S/N \$	2,400.00	✓✓
8	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00 280	✓
9	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAYING OF LHS FRONT DOOR.	S/N \$	280.00	x
10	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAL BELT AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS.	S/N \$	3,600.00	✓
11	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT. TO REPAIR RHS FRONT WHEEL HOUSING TOP MOUNTING AND BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSTION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$	11,400.00 4500	✓
12	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, HINGES, RHS FRONT FENDER TOP SUPPORT, BOTH FRONT DOOR AND BOTH UPPER A-PILLAR.	\$	8,000.00 3185	5 x 550 = 2750 Hinge x 02 = 160. Fender top support = 275
SUB TOTAL LABOUR CHARGES		: \$	<u>26,080.00</u>	3185 ✓

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 9247 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO TOW BACK THE VEHICLE FROM THE ACCIDENT SCENE.	S/N \$	280.00	X
14	TO DISMANTLE AND RENEW FRONT WINDSCREEN.	S/N \$	480.00	✓✓
15	TO APPLY FRONT WINDSCREEN SOLAR FILM.	S/N \$	400.00	✓✓
16	TO CARRY OUT WATER SEEPAGE TEST AFTER WINDSCREEN REPLACEMENT.	S/N \$	200.00 150	✓
17	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	✓✓
18	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	✓✓
TOTAL LABOUR CHARGES		:	\$ 35,724.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9247 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PA	
			S/NETT	
1	FRONT BUMPER <i>Distorted</i>	1	\$ 3,012.00 ✓	2409.60
2	FRONT BUMPER FIXING PARTS <i>Not new</i>	1	\$ 659.00 ✗	
3	FRONT BUMPER CLOSING ELEMENT - CENTER <i>form</i>	1	\$ 248.00 ✓	198.40
4	FRONT BUMPER ADAPTER - LH / RH <i>Distorted</i>	2	\$ 88.00 ✓	70.24
5	FRONT BUMPER REINFORCEMENT - LH / RH <i>RH Damaged</i>	2	\$ 250.00 ?	99.60 ✓
6	FRONT BUMPER GRILLE - LOWER CENTER <i>Deltd</i>	1	\$ 171.00 ✓	136.40
7	FRONT BUMPER CLOSING ELEMENT - LOWER <i>Missing</i>	1	\$ 235.00 ✓	187.60
8	FRONT BUMPER SPOILER <i>cracked</i>	1	\$ 282.00 ✓	225.20
9	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 485.00 ✓	387.60
10	FRONT BUMPER AIR GUIDE INNER - RH	1	\$ 33.00 ✓	25.84
11	FRONT BUMPER AIR GUIDE OUTER - RH	1	\$ 24.00 ✓	18.48
12	RADIATOR GRILLE <i>Cracked</i>	1	\$ 2,460.00 ✓	1968
13	RADIATOR GRILLE CENTER COVER <i>new</i>	1	\$ 61.00 ✗	
14	RADIATOR GRILLE COVER CAP <i>new</i>	1	\$ 55.00 ✗	
15	RADIATOR GRILLE BRACKET <i>new</i>	1	\$ 104.00 ✗	
16	RADIATOR GRILLE SECURING PLATE	1	\$ 93.00 ✗	
17	FRONT CAMERA <i>Not new</i>	1	\$ 1,003.00 ✗	
18	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	1	\$ 252.00 ✓	201.60
19	FRONT BUMPER REINFORCEMENT BEAM <i>Bent</i>	1	\$ 1,076.00 ✓	860.80
20	FRONT BUMPER REINFORCEMENT BEAM SUPPORT - LH / RH <i>new</i>	2	\$ 67.00 ✓	53.60
SUB TOTAL SPARE PARTS		:	\$ 10,658.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9247 X

S/N	PARTS DESCRIPTION	QTY		DAMAGED PA S/NETT
21	FRONT BUMPER REINFORCEMENT BEAM SUPPORT BRACKET - RH <i>Dmgd</i>	1	\$	61.00 ✓ 48.32
22	FRONT BUMPER GUIDE SECTION - RH <i>Dmgd</i>	1	\$	50.00 ✓ 39.52
23	FRONT BUMPER TOP COVER <i>Relnd</i>	1	\$	140.00 ✓ 112
24	FRONT BUMPER TOP COVER FOAM FILLER PIECE - RH <i>missing</i>	1	\$	42.00 ✓ 33.60
25	AIR COND STICKER <i>3 New</i>	1	\$	34.00 ✓ 26.96
26	OIL COMPLY STICKER	1	\$	34.00 ✓ 27.20
27	PEDESTRIAN PROTECTION WARNING SIGN STICKER <i>Not mee.</i>	1	\$	34.00 ? X
28	HORN - RH <i>Dmgd</i>	1	\$	154.00 ✓ 123.20
29	HORN SUPPORT - RH <i>Bent</i>	1	\$	53.00 ✓ 41.76
30	FRONT PARKING AID SENSOR <i>Dmgd 1 piece</i>	2	\$	488.00 ✓ 484 195.20
31	FRONT PARKING AID SENSOR SIDE <i>Dmgd</i>	1	\$	244.00 ✓ 232.96
32	FRONT PARKING AID SENSOR SEAL RING <i>New</i>	6	\$	15.00 ✓ 12.00
33	FRONT BUMPER WIRING SET <i>Not mee.</i>	1	\$	642.00 ? X
34	BONNET <i>Distorted</i>	1	\$	5,846.00 ✓ 4676.80
35	BONNET HINGE - LH / RH <i>Bent</i>	2	\$	382.00 ✓ 305.60
36	BONNET ATTACHMENT PARTS <i>New</i>	1	\$	243.00 ✓ 4.
37	BONNET ABSORBER <i>1 piece Dmgd</i>	2	\$	256.00 128 204.80
38	BONNET IMPACT PROTECTION - LH / RH <i>3 New</i>	2	\$	44.00 ✓ 34.32
39	BONNET IMPACT PROTECTION - CENTER	1	\$	50.00 ✓ 39.36
40	BONNET FLAP SOUND ABSORBER <i>crumpled</i>	1	\$	353.00 ✓ 282.40
SUB TOTAL SPARE PARTS			:	\$ 9,165.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9247 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET STRIKER - RH <i>Bent</i>	1	\$ 123.00 ✓	98
42	BONNET HINGE COVER - RH <i>Dmd</i>	1	\$ 6.00 ✓	4.40
43	FRONT FENDER UPPER INNER COVER - RH <i>Distorted</i>	1	\$ 36.00 ✓	28.48
44	HEADLIGHT COVER <i>missing</i>	1	\$ 49.00 ✓	38.64
45	BONNET SEAL - RH <i>nee</i>	1	\$ 33.00 ?	26.32 ✓
46	PLENUM CHAMBER COVER <i>Behind</i>	1	\$ 222.00 ✓	177.20
47	FRONT FENDER UPPER OUTER COVER - RH <i>missing</i>	1	\$ 40.00 ✓	31.44
48	BONNET LOCK MICRO-SWITCH <i>2nd</i>	1	\$ 239.00 ✓	190.80
49	BONNET BOWDEN CABLE - CENTER <i>nee Damaged</i>	1	\$ 64.00 ?	50.56 ✓
50	BONNET RELEASE ELEMENT <i>Damaged</i>	1	\$ 65.00 ?	51.44 ✓
51	BONNET RELEASE LEVER <i>Not nee</i>	1	\$ 15.00 ?	X
52	BONNET LOCK CABLE <i>nee nee</i>	1	\$ 82.00 ?	X
53	BONNET RELEASE CABLE COVER <i>Damaged</i>	1	\$ 11.00 ?	8.56 ✓
54	BONNET BRACKET <i>nee nee</i>	1	\$ 51.00 ?	X
55	BONNET LOCK CABLE GRIP <i>nee nee</i>	1	\$ 71.00 ?	X
56	FRONT FENDER - RH <i>Distorted</i>	1	\$ 1,649.00 ✓	1319.20
57	FRONT FENDER BRACE - RH <i>Distorted</i>	1	\$ 137.00 ✓	109.60
58	FRONT FENDER BRACKET - RH UPPER <i>Distorted</i>	1	\$ 49.00 ✓	38.64
59	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 60.00 ✓	47.28
60	FRONT FENDER ATTACHMENT PARTS <i>Dmd</i>	1	\$ 44.00 ✓	35.20
SUB TOTAL SPARE PARTS		:	\$ 3,046.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9247 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	FRONT WHEEL HOUSING LINER <i>tom</i>	1	\$ 299.00	✓ 238.80
62	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 74.00	✓ 59.20
63	FRONT WHEEL SPOILER - RH <i>Distal</i>	1	\$ 185.00	✓ 147.60
64	FRONT WHEEL SPOILER STONE CHIP GUARD - RH <i>new</i>	1	\$ 57.00	✓ 45.28
65	FRONT WHEEL SPOILER TRIM BRACKET - RH <i>Distal</i>	1	\$ 45.00	✓ 35.36
66	HEADLIGHT MOUNTING - RH <i>3 smashed</i>	1	\$ 132.00	✓ 105.20
67	HEADLIGHT MATRIX BEAM - RH	1	\$ 9,172.00	✓ 7337.60
68	HEADLIGHT HOSE - RH <i>new</i>	1	\$ 33.00	+
69	HEADLIGHT COVER CAP - RH <i>not nec.</i>	1	\$ 65.00	✓ X
70	SPACER <i>Distal</i>	2	\$ 90.00	✓ 71.04
71	LIFT CYLINDER - RH <i>3 smashed</i>	1	\$ 217.00	✓ 173.60
72	LIFT CYLINDER BRACKET - RH <i>3 missing</i>	1	\$ 7.00	✓ 5.44
73	LIFT CYLINDER ELBOW FITTING UPPER <i>not nec.</i>	1	\$ 33.00	✓ 26.08
74	LIFT CYLINDER HOSE <i>tom</i>	1	\$ 204.00	✓ 162.80 ✓
75	LIFT CYLINDER T-PIECE <i>Nec</i>	1	\$ 17.00	✓ 13.44 ✓
76	LIFT CYLINDER ELBOW FITTING LOWER <i>Nec</i>	1	\$ 29.00	✓ 22.48 ✓
77	LIFT CYLINDER COUPLING ELEMENT - STRAIGHT <i>3 nec</i>	2	\$ 26.00	+
78	LIFT CYLINDER CONNECTING PIECE - STRAIGHT <i>1 nec</i>	1	\$ 16.00	+
79	WATER RESERVOIR PUMP <i>cracked</i>	1	\$ 171.00	✓ 136.80 ✓
80	WASH WATER RESERVOIR <i>Distal</i>	1	\$ 208.00	✓ 166.40
SUB TOTAL SPARE PARTS		:	\$ 11,080.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAL@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9247 X

S/N	PARTS DESCRIPTION	QTY		DAMAGED PA	
				S/NETT	
81	WATER RESERVOIR WINDSCREEN WASHER SYSTEM PUMP <i>Not</i>	1	\$	137.00 <i>+</i>	
82	WATER RESERVOIR FUEL FILLER NECK <i>Deformed.</i>	1	\$	202.00 <i>+</i>	161.60 ✓
83	WATER RESERVOIR STRAINER <i>Nec</i>	1	\$	29.00 <i>+</i>	22.88 ✓
84	WATER RESERVOIR END CAP <i>Missing.</i>	1	\$	20.00 <i>+</i>	15.44 ✓
85	LOCK CARRIER <i>cracked.</i>	1	\$	1,368.00 <i>+</i>	1094.40
86	LOCK CARRIER SUPPPORT - RH <i>Damaged</i>	1	\$	25.00 <i>?</i>	38.88 ✓
87	A/C CONDENSER <i>Warpped.</i>	1	\$	683.00 <i>?</i>	546.00 ✓
88	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1	\$	26.00 <i>✓</i>	20.40
89	EXTERNAL TEMPERATURE SENSOR <i>new</i>	1	\$	64.00 <i>+</i>	
90	CHARGE AIR COOLER <i>new</i>	1	\$	654.00 <i>+</i>	
91	CHARGE AIR COOLER PRESSURE HOSE - RH <i>new</i>	1	\$	341.00 <i>+</i>	
92	RADIATOR <i>Leaking.</i>	1	\$	1,010.00 <i>+</i>	808 ✓
93	RADIATOR COOLANT <i>new</i>	6	\$	282.00 <i>✓</i>	225.60
94	RADIATOR AIR GUIDE - RH <i>torn</i>	1	\$	44.00 <i>✓</i>	34.72
95	RADIATOR AIR GUIDE - UPPER <i>cracked</i>	1	\$	34.00 <i>✓</i>	27.04
96	RADIATOR AIR GUIDE - LOWER <i>Not Nec</i>	1	\$	38.00 <i>?</i>	X
97	INTAKE AIR DUCT LOWER <i>cracked</i>	1	\$	51.00 <i>✓</i>	40.08
98	INTAKE AIR DUCT UPPER <i>cracked</i>	1	\$	92.00 <i>✓</i>	73.52
99	AIR FILTER BOX <i>ok</i>	1	\$	328.00 <i>✓</i>	262.40
100	AIR MASS METER <i>not nec</i>	1	\$	627.00 <i>?</i>	X
SUB TOTAL SPARE PARTS		:	\$	6,055.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9247 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PA	S/NETT
101	INTAKE HOSE <i>Ne u</i>	1 S	174.00	+
102	FRONT FENDER TOP SUPPORT - RH UPPER <i>Buckled</i>	1 S	291.00	✓ 232.80
103	FRONT FENDER TOP SUPPORT CLOSING ELEMENT - RH UPPER <i>Buckled</i>	1 S	83.00	✓ 65.84
104	NOISE INSULATION PLATE - RH <i>Buckled</i>	1 S	28.00	✓ 22.32
105	FRONT DOOR - RH <i>Repis</i>	1 S	4,489.00	+
106	FRONT DOOR OUTER SEAL - RH	1 S	191.00	+
107	FRONT DOOR ATTACHMENT PARTS <i>xre m</i>	1 S	379.00	+
108	FRONT DOOR CATCH - RH	1	TBC	+
109	TYRE PRESSURE DATA PLATE <i>xre m</i>	1 S	34.00	+
110	WINDSCREEN WATER DEFLECTOR STRIP - LH / RH <i>RH Deformed</i>	2 S	132.00	66. 152.80
111	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH / RH OUTER <i>2H Cut</i>	2 S	448.00	224. 178.80
112	FRONT DOOR WINDOW GUIDE TRIM STRIP - LH / RH <i>xre m</i>	2 S	574.00	+
113	STEERING WHEEL AIRBAG UNIT	1 S	5,046.00	✓ 4036.80
114	PASSENGER SIDE AIRBAG UNIT	1 S	4,341.00	✓ 3472.80
115	HEAD AIRBAG UNIT - LH / RH	2 S	3,872.00	✓ 3097.60
116	AIRBAG CONTROL UNIT	1 S	3,219.00	✓ 2575.20
117	AIRBAG LOCK CARRIER CRASH SENSOR - LH / RH <i>Activated</i>	2 S	764.00	✓ 716.48
118	FUSE UNIT <i>Activated</i>	1 S	590.00	✓ 472.00
119	SEAL BELT - LH / RH <i>Activated</i>	2 S	2,454.00	✓ 1963.20
120	SEAT BELT HEIGHT ADJUSTER - LH / RH <i>Damaged</i>	2 S	383.00	✓ 612.80 ✓

SUB TOTAL SPARE PARTS

: \$ 27,492.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9247 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PA	
			S/NETT	
121	STEERING WHEEL <i>int</i>	1	\$ 2,810.00 ✓	2248
122	SEAT BELT DASHBOARD <i>top</i>	1	\$ 7,693.00 ✓	6154.40
123	ROOF LINER <i>crumpled</i>	1	\$ 2,896.00 ✓	2316.80
124	FRONT GRAB HANDLE - LH / RH <i>Damaged</i>	2	TBC ?	280.16 ✓
125	REAR GRAB HANDLE - LH / RH <i>Damaged</i>	2	TBC ?	280.16 ✓
126	A-PILLAR TRIM - LH / RH <i>Del-d</i>	2	\$ 502.00 ?	401.60 ✓
127	B-PILLAR TRIM UPPER - LH / RH <i>Not rec</i>	2	\$ 536.00 ?	X
128	C-PILLAR TRIM - LH / RH <i>Not rec</i>	2	\$ 524.00 ?	X
129	D-PILLAR TRIM - LH / RH <i>Not rec</i>	2	\$ 520.00 ?	X
130	FRONT ALUMINIUM RIM <i>int</i>	1	\$ 1,847.00 ✓	1477.60
131	FRONT RUBBER VALVE <i>Not rec</i>	4	\$ 15.00 ✓	11.84 ✓
132	FRONT SUSPENSION SUBFRAME <i>Not rec</i>	1	\$ 2,096.00 ?	X
133	FRONT SUSPENSION SUBFRAME CONSOLE <i>Not rec</i>	1	\$ 622.00 ?	X
134	FRONT WISHBONE LINK - RH <i>Not rec</i>	1	\$ 605.00 ?	X
135	WISHBONE SUSPENSION GUIDE <i>Not rec</i>	1	\$ 1,057.00 ?	X
136	WISHBONE GUIDE UPPER RH - FRONT / REAR <i>Not rec</i>	2	\$ 844.00 ?	X
137	WISHBONE WHEEL BEARING HOUSING - RH <i>Not rec</i>	1	\$ 999.00 ?	X
138	WISHBONE SWIVEL JOINT <i>Not rec</i>	1	\$ 153.00 ?	X
139	WISHBONE WHEEL HUB <i>Not rec</i>	1	\$ 498.00 ?	X
140	WISHBONE FLANGE DOUBLE BALL BEARING <i>Not rec</i>	1	\$ 273.00 ?	X
SUB TOTAL SPARE PARTS		:	\$ 24,490.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NGRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9247 X

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
141	SUSPENSION FORKS - RH <i>Nec</i>	1	\$ 410.00	? X
142	COUPLING ROD <i>Nec</i>	2	\$ 258.00	? X
143	FRONT ANTI-ROLL BAR <i>Nec</i>	1	\$ 393.00	? X
144	GAS SHOCK ABSORBER <i>Nec</i>	1	\$ 1,366.00	? X
145	FRONT SPEED SENSOR <i>Nec</i>	1	\$ 129.00	? X
146	DRIVE SHAFT <i>Nec</i>	1	\$ 2,999.00	X
147	TRACK ROD <i>Nec</i>	1	\$ 157.00	? X
148	TIE ROD END - RH <i>Nec</i>	1	\$ 217.00	? X
149	ENGINE UNDERSHIELD <i>torn</i>	1	\$ 709.00	? 567.20 ✓
150	FRONT WINDSCREEN <i>cracked</i>	1	\$ 1,875.00	✓ 1500
151	GEL FOIL FOR RAIN SENSOR <i>Nec</i>	1	\$ 130.00	✓ 104
152	GLASS PRIMER <i>Nec</i>	1	\$ 22.00	✓ 17.36
153	FRONT WINDSCREEN SEALANT <i>Nec</i>	S/N	\$ 200.00	✓
154	FRONT NO PLATE <i>Nec</i>	S/N	\$ 60.00	✓
155	ARYLIC SEALANT <i>Nec</i>	S/N	\$ 180.00	✓
156	CAVITY WAX <i>Nec</i>	S/N	\$ 140.00	✓
157	STONE CHIP <i>Nec</i>	S/N	\$ 180.00	✓
158	METAL FILLER POWDER <i>Nec</i>	S/N	\$ 280.00	✓
159	RHS FRONT TYRE <i>xxx Punctured</i>	S/N	TBC	✓ 410
160	SUNDRIES <i>Nec</i>		\$ 600.00	? 485.84 ✓
TOTAL SPARE PARTS		:	\$ 102,291.00	
TOTAL LABOUR CHARGES		:	\$ 35,724.00	
GRAND TOTAL		:	\$ 138,015.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

Adrian L
23/02/22

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Not Authorised

25 Days H.S.
21 Days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT