

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

Xiao Chan.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0129/2022/JT

17-Mar-22

CHANG

1 of 1

SMY 9247 X

AUDI A6 DESIGN 2.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND TRANSFER LHS HEADLIGH'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250 ✓
2	TO RENEW LHS FRONT FENDER.	\$ 1,200.00	500 ✓
3	TO CUT OUT AND WELD RHS A-PILLAR BRACKET. ✓	\$ 1,200.00	250 ✓
4	TO RESPRAY LHS FRONT FENDER AND RHS A-PILLAR BRACKET.	\$ 1,600.00	700 ✓
5	TO RENEW POTENTIAL DISTRIBUTOR AND FRONTAL WIRING CONNECTOR. TO INSPECT, CHECK AND REPAIR WIRING HARNESS.	S/N \$ 780.00	✓
Parts			
1	HEADLIGHT MOUNTING - LH <i>ambd</i>	\$ 132.00	✓ 105.20
2	REINFORCEMENT BEAM SUPPORT - LH <i>ambd</i>	\$ 67.00	✓ 53.44
3	A-PILLAR BRACKET - RH <i>new</i>	\$ 99.00	✓ 98
4	FRONT FENDER - LH <i>ambd</i>	\$ 1,649.00	✓ 1319.20
5	BONNET STRIKER - LH <i>best</i>	\$ 123.00	✓ 98
6	BONNET LOCK - LH <i>ambd</i>	\$ 239.00	✓ 190.80
7	WATER RESERVOIR SEAL <i>new</i>	\$ 66.00	✓ 52.40
8	MATRIX LED HEADLIGHT - LH <i>let</i>	\$ 9,172.00	✓ 7337.60
9	RADIATOR AIR GUIDE - LH <i>torn</i>	\$ 44.00	✓ 34.72
10	RADIATOR SUPPORT - LH <i>torn</i>	\$ 25.00	✓ 20
11	POTENTIAL DISTRIBUTOR <i>ambd</i>	\$ 471.00	✓ 376.40
12	WIRE BUTT CONNECTOR SET <i>new</i>	\$ 228.00	✓ 182.40
13	HEADLIGHT WIRE CONNECTOR <i>ambd</i>	\$ 18.00	✓ 13.84
14	1 SET SINGLE WIRE - 1,2 <i>snapped</i>	\$ 95.00	✓ 75.84
15	1 SET SINGLE WIRE <i>snapped</i>	\$ 95.00	✓ 75.84
16	WIRE CONNECTOR - 3 PIN YELLOW <i>ambd</i>	\$ 26.00	✓ 20.08
17	1 SET SINGLE WIRE - 2,8 <i>snapped</i>	\$ 79.00	✓ 62.88
18	1 SET SINGLE WIRE - 1,5 <i>snapped</i>	\$ 95.00	✓ 37.92
19	WIRE CONNECTOR - 3 PIN YELLOW <i>ambd</i>	\$ 26.00	✓ 20.80
20	DOOR WIRING CONNECTOR - 27 PIN <i>ambd</i>	\$ 37.00	✓ 29.60
GRAND TOTAL		\$ 17,966.00	

Add 4 days for fender replacement, repair of A pillar bracket and wiring. 17/03/22

For Premium Automobiles Pte Ltd



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 9247 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,700.00	✓
4	TO CARRY OUT PRESSURISE, VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	?
5	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,800.00	✗
6	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER.	S/N \$ 800.00	✓
SUB TOTAL LABOUR CHARGES		: \$ 7,380.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 9247 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO SETUP THE VEHICLE CAR O-LINER TO FACILITATE THE REPAIR.	S/N \$ 2,400.00	✓
8	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280.00
9	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAYING OF LHS FRONT DOOR.	S/N \$ 280.00	X
10	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAL BELT AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS.	S/N \$ 3,600.00	✓
11	TO DISMANILE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT. TO REPAIR RHS FRONT WHEEL HOUSING TOP MOUNTING AND BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSTION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 11,400.00	4500.
12	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, HINGES, RHS FRONT FENDER TOP SUPPORT, BOTH FRONT DOOR AND BOTH UPPER A-PILLAR.	\$ 8,000.00	3185
SUB TOTAL LABOUR CHARGES		\$ 26,080.00	5 x 550 = 2750 Hinge x 02 = 160. Fender top support = 275 3185

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 9247 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO TOW BACK THE VEHICLE FROM THE ACCIDENT SCENE.	S/N \$	280.00	X
14	TO DISMANTLE AND RENEW FRONT WINDSCREEN.	S/N \$	480.00	✓
15	TO APPLY FRONT WINDSCREEN SOLAR FILM.	S/N \$	400.00	✓
16	TO CARRY OUT WATER SEEPAGE TEST AFTER WINDSCREEN REPLACEMENT.	S/N \$	200.00 150	
17	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	✓
18	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 35,724.00</u>	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

E-MAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9247 X

S/N	PARTS DESCRIPTION	QTY		DAMAGED PA	
				S/NETT	
1	FRONT BUMPER <i>Distorted</i>	1	\$	3,012.00	✓
2	FRONT BUMPER FIXING PARTS <i>Not new</i>	1	\$	659.00	✗
3	FRONT BUMPER CLOSING ELEMENT - CENTER <i>form</i>	1	\$	248.00	✓
④	FRONT BUMPER ADAPTER - LH / RH <i>Distorted</i>	2	\$	88.00	✓ <i>h.s.</i>
⑤	FRONT BUMPER REINFORCEMENT - LH / RH <i>RH Bent</i>	2	\$	250.00	125 <i>h.s.</i>
6	FRONT BUMPER GRILLE - LOWER CENTER <i>Delud</i>	1	\$	171.00	✓
7	FRONT BUMPER CLOSING ELEMENT - LOWER <i>Missing</i>	1	\$	235.00	✓
8	FRONT BUMPER SPOILER <i>cracked</i>	1	\$	282.00	✓
9	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$	485.00	✓
10	FRONT BUMPER AIR GUIDE INNER - RH	1	\$	33.00	✓
11	FRONT BUMPER AIR GUIDE OUTER - RH	1	\$	24.00	✓
12	RADIATOR GRILLE <i>Cracked.</i>	1	\$	2,460.00	✓
13	RADIATOR GRILLE CENTER COVER <i>new</i>	1	\$	61.00	✗
14	RADIATOR GRILLE COVER CAP <i>new</i>	1	\$	55.00	✓
15	RADIATOR GRILLE BRACKET <i>new</i>	1	\$	104.00	✗
16	RADIATOR GRILLE SECURING PLATE	1	\$	93.00	✗
17	FRONT CAMERA <i>Not new</i>	1	\$	1,003.00	✗
18	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	1	\$	252.00	✓
19	FRONT BUMPER REINFORCEMENT BEAM <i>Bent</i>	1	\$	1,076.00	✓
20	FRONT BUMPER REINFORCEMENT BEAM SUPPORT - LH / RH <i>new</i>	2	\$	67.00	✓
SUB TOTAL SPARE PARTS			:	\$	<u>10,658.00</u>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NCRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9247 X

S/N	PARTS DESCRIPTION	QTY		DAMAGED PA	
				S/NETT	
21	FRONT BUMPER REINFORCEMENT BEAM SUPPORT BRACKET - RH <i>2nd</i>	1	\$	61.00	✓
22	FRONT BUMPER GUIDE SECTION - RH <i>2nd</i>	1	\$	50.00	✓
23	FRONT BUMPER TOP COVER <i>2nd</i>	1	\$	140.00	✓
24	FRONT BUMPER TOP COVER FOAM FILLER PIECE - RH <i>missing</i>	1	\$	42.00	✓
25	AIR COND STICKER <i>3 New</i>	1	\$	34.00	✓
26	OIL COMPLY STICKER	1	\$	34.00	✓
27	PEDESTRIAN PROTECTION WARNING SIGN STICKER ?	1	\$	34.00	?
28	HORN - RH <i>2nd</i>	1	\$	154.00	✓
29	HORN SUPPORT - RH <i>2nd</i>	1	\$	53.00	✓
30	FRONT PARKING AID SENSOR <i>2nd 1 piece</i>	2	\$	480.00 244	✓
31	FRONT PARKING AID SENSOR SIDE <i>2nd</i>	1	\$	244.00	✓
32	FRONT PARKING AID SENSOR SEAL RING <i>new</i>	6	\$	15.00	✓
33	FRONT BUMPER WIRING SET ?	1	\$	642.00	?
34	BONNET <i>Distorted</i>	1	\$	5,846.00	✓
35	BONNET HINGE - LH / RH <i>2nd</i>	2	\$	382.00	✓
36	BONNET ATTACHMENT PARTS <i>new</i>	1	\$	243.00	+
37	BONNET ABSORBER <i>1 piece 2nd (+ 1pc) 2nd LH</i>	2	\$	256.00 256	✓ <i>256</i>
38	BONNET IMPACT PROTECTION - LH / RH <i>3 New</i>	2	\$	44.00	✓
39	BONNET IMPACT PROTECTION - CENTER	1	\$	50.00	✓
40	BONNET FLAP SOUND ABSORBER <i>crumpled</i>	1	\$	350.00	✓
SUB TOTAL SPARE PARTS			:	\$	9,165.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9247 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET STRIKER - RH <i>Best</i>	1	\$ 123.00	✓
42	BONNET HINGE COVER - RH <i>Dmd</i>	1	\$ 6.00	✓
43	FRONT FENDER UPPER INNER COVER - RH <i>Distorted</i>	1	\$ 36.00	✓
44	HEADLIGHT COVER <i>missing</i>	1	\$ 49.00	✓
45	BONNET SEAL - RH <i>nu</i>	1	\$ 33.00	✓
46	PLENUM CHAMBER COVER <i>Rehnd</i>	1	\$ 222.00	✓
47	FRONT FENDER UPPER OUTER COVER - RH <i>missing</i>	1	\$ 40.00	✓
48	BONNET LOCK MICRO-SWITCH <i>Rehnd</i>	1	\$ 239.00	✓
49	BONNET BOWDEN CABLE - CENTER <i>Rehnd</i>	1	\$ 64.00	✓
50	BONNET RELEASE ELEMENT <i>Rehnd</i>	1	\$ 65.00	✓
51	BONNET RELEASE LEVER ?	1	\$ 15.00	?
52	BONNET LOCK CABLE <i>Rehnd</i>	1	\$ 82.00	✓
53	BONNET RELEASE CABLE COVER <i>Rehnd</i>	1	\$ 11.00	✓
54	BONNET BRACKET ?	1	\$ 51.00	?
55	BONNET LOCK CABLE GRIP ?	1	\$ 71.00	?
56	FRONT FENDER - RH <i>Distorted</i>	1	\$ 1,649.00	✓
57	FRONT FENDER BRACE - RH <i>Distorted</i>	1	\$ 137.00	✓
58	FRONT FENDER BRACKET - RH UPPER <i>Distorted</i>	1	\$ 49.00	✓
59	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 60.00	✓
60	FRONT FENDER ATTACHMENT PARTS <i>Dmd</i>	1	\$ 44.00	✓
SUB TOTAL SPARE PARTS		:	\$ 3,046.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9247 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	FRONT WHEEL HOUSING LINER <i>tom</i>	1	\$ 299.00	✓
62	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Ne</i>	1	\$ 74.00	✓
63	FRONT WHEEL SPOILER - RH <i>Distal</i>	1	\$ 185.00	✓
64	FRONT WHEEL SPOILER STONE CHIP GUARD - RH <i>Ne</i>	1	\$ 57.00	✓
65	FRONT WHEEL SPOILER TRIM BRACKET - RH <i>Dist</i>	1	\$ 45.00	✓
66	HEADLIGHT MOUNTING - RH <i>3 smashed</i>	1	\$ 132.00	✓
67	HEADLIGHT MATRIX BEAM - RH	1	\$ 9,172.00	✓
68	HEADLIGHT HOSE - RH <i>new</i>	1	\$ 33.00	+
69	HEADLIGHT COVER CAP - RH <i>?</i>	1	\$ 65.00	?
70	SPACER <i>3mgd</i>	2	\$ 90.00	✓
71	LIFT CYLINDER - RH <i>Smashed</i>	1	\$ 217.00	✓
72	LIFT CYLINDER BRACKET - RH <i>3 smashed</i>	1	\$ 7.00	✓
73	LIFT CYLINDER ELBOW FITTING UPPER <i>atom could</i>	1	\$ 33.00	✓
74	LIFT CYLINDER HOSE <i>3x100 tom</i>	1	\$ 204.00	✓
75	LIFT CYLINDER T-PIECE <i>ne</i>	1	\$ 17.00	✓
76	LIFT CYLINDER ELBOW FITTING LOWER <i>atom m</i>	1	\$ 29.00	✓
77	LIFT CYLINDER COUPLING ELEMENT - STRAIGHT <i>3x100 m</i>	1	\$ 26.00	+
78	LIFT CYLINDER CONNECTING PIECE - STRAIGHT <i>3x100 m</i>	1	\$ 16.00	✓
79	WATER RESERVOIR PUMP <i>atom could</i>	1	\$ 171.00	✓
80	WASH WATER RESERVOIR <i>Distal</i>	1	\$ 208.00	✓
SUB TOTAL SPARE PARTS		:	\$ 11,080.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9247 X

			DAMAGED PA	
S/N	PARTS DESCRIPTION	QTY	S/NETT	
81	WATER RESERVOIR WINDSCREEN WASHER SYSTEM PUMP <i>not here</i>	1	\$	137.00 <i>+</i>
82	WATER RESERVOIR FUEL FILLER NECK <i>not here Delnd</i>	1	\$	202.00 <i>+</i>
83	WATER RESERVOIR STRAINER <i>not here</i>	1	\$	29.00 <i>+</i>
84	WATER RESERVOIR END CAP <i>not here missing</i>	1	\$	20.00 <i>+</i>
85	LOCK CARRIER <i>cracked.</i>	1	\$	1,368.00 <i>+</i>
86	LOCK CARRIER SUPPORT - RH <i>not here</i>	1	\$	25.00 <i>+</i>
87	A/C CONDENSER <i>wrapped.</i>	1	\$	683.00 <i>+</i>
88	OUTSIDE TEMPERATURE SENSOR BRACKET <i>not here</i>	1	\$	26.00 <i>+</i>
89	EXTERNAL TEMPERATURE SENSOR <i>not here</i>	1	\$	64.00 <i>+</i>
90	CHARGE AIR COOLER <i>not here</i>	1	\$	654.00 <i>+</i>
91	CHARGE AIR COOLER PRESSURE HOSE - RH <i>not here</i>	1	\$	341.00 <i>+</i>
92	RADIATOR <i>not here leaking</i>	1	\$	1,010.00 <i>+</i>
93	RADIATOR COOLANT <i>not here</i>	6	\$	282.00 <i>+</i>
94	RADIATOR AIR GUIDE - RH <i>torn</i>	1	\$	44.00 <i>+</i>
95	RADIATOR AIR GUIDE - UPPER <i>cracked</i>	1	\$	34.00 <i>+</i>
96	RADIATOR AIR GUIDE - LOWER <i>?</i>	1	\$	38.00 <i>+</i>
97	INTAKE AIR DUCT LOWER <i>cracked</i>	1	\$	51.00 <i>+</i>
98	INTAKE AIR DUCT UPPER <i>cracked</i>	1	\$	92.00 <i>+</i>
99	AIR FILTER BOX <i>not here</i>	1	\$	328.00 <i>+</i>
100	AIR MASS METER <i>not here</i>	1	\$	627.00 <i>+</i>
SUB TOTAL SPARE PARTS		:	\$	6,055.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9247 X

S/N	PARTS DESCRIPTION	QTY		DAMAGED PA	
				S/NETT	
101	INTAKE HOSE <i>new</i>	1	\$	174.00	+
102	FRONT FENDER TOP SUPPORT - RH UPPER <i>Buckled</i>	1	\$	291.00	✓
103	FRONT FENDER TOP SUPPORT CLOSING ELEMENT - RH UPPER <i>Buckled</i>	1	\$	83.00	✓
104	NOISE INSULATION PLATE - RH <i>Buckled</i>	1	\$	28.00	✓
105	FRONT DOOR - RH <i>Repair</i>	1	\$	4,489.00	+
106	FRONT DOOR OUTER SEAL - RH	1	\$	191.00	+
107	FRONT DOOR ATTACHMENT PARTS <i>new</i>	1	\$	379.00	+
108	FRONT DOOR CATCH - RH	1		TBC	+
109	TYRE PRESSURE DATA PLATE <i>new</i>	1	\$	34.00	+
110	WINDSCREEN WATER DEFLECTOR STRIP - LH / RH <i>RH Deformed</i>	2	\$	132.00	66.
111	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH / RH OUTER <i>RH Cut</i>	2	\$	448.00	224.
112	FRONT DOOR WINDOW GUIDE TRIM STRIP - LH / RH <i>new</i>	2	\$	574.00	+
113	STEERING WHEEL AIRBAG UNIT	1	\$	5,046.00	✓
114	PASSENGER SIDE AIRBAG UNIT	1	\$	4,341.00	✓
115	HEAD AIRBAG UNIT - LH / RH	2	\$	3,872.00	✓
116	AIRBAG CONTROL UNIT	1	\$	3,219.00	✓
117	AIRBAG LOCK CARRIER CRASH SENSOR - LH / RH <i>Activated</i>	2	\$	764.00	✓
118	FUSE UNIT <i>Activated</i>	1	\$	590.00	✓
119	SEAL BELT - LH / RH <i>Activated</i>	2	\$	2,454.00	✓
120	SEAT BELT HEIGHT ADJUSTER <i>LH RH new</i>	2	\$	383.00	+
SUB TOTAL SPARE PARTS			:	\$	27,492.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9247 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PA	
			S/NETT	
121	STEERING WHEEL <i>ut</i>	1	\$	2,810.00 ✓
122	SEAT BELT DASHBOARD <i>torn</i>	1	\$	7,693.00 ✓
123	ROOF LINER <i>crumpled</i>	1	\$	2,896.00 ✓
124	FRONT GRAB HANDLE - LH / RH ?	2	TBC	?
125	REAR GRAB HANDLE - LH / RH ?	2	TBC	?
126	A-PILLAR TRIM - LH / RH ?	2	\$	502.00 ?
127	B-PILLAR TRIM UPPER - LH / RH ?	2	\$	536.00 ?
128	C-PILLAR TRIM - LH / RH ?	2	\$	524.00 ?
129	D-PILLAR TRIM - LH / RH ?	2	\$	520.00 ?
130	FRONT ALUMINIUM RIM <i>ut</i>	1	\$	1,847.00 ✓
131	FRONT RUBBER VALVE <i>ut (1pc) m</i>	4	\$	15.00 ✓ <i>hls</i>
132	FRONT SUSPENSION SUBFRAME ?	1	\$	2,096.00 ?
133	FRONT SUSPENSION SUBFRAME CONSOLE ?	1	\$	622.00 ?
134	FRONT WISHBONE LINK - RH ?	1	\$	605.00 ?
135	WISHBONE SUSPENSION GUIDE ?	1	\$	1,057.00 ?
136	WISHBONE GUIDE UPPER RH - FRONT / REAR ?	2	\$	844.00 ?
137	WISHBONE WHEEL BEARING HOUSING - RH ?	1	\$	999.00 ?
138	WISHBONE SWIVEL JOINT ?	1	\$	153.00 ?
139	WISHBONE WHEEL HUB ?	1	\$	498.00 ?
140	WISHBONE FLANGE DOUBLE BALL BEARING ?	1	\$	273.00 ?
SUB TOTAL SPARE PARTS		:	\$	24,490.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9247 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
141	SUSPENSION FORKS - RH ?	1 \$	410.00 ?	
142	COUPLING ROD ?	2 \$	258.00 ?	
143	FRONT ANTI-ROLL BAR ?	1 \$	393.00 ?	
144	GAS SHOCK ABSORBER ?	1 \$	1,366.00 ?	
145	FRONT SPEED SENSOR ?	1 \$	129.00 ?	
146	DRIVE SHAFT <i>new</i>	1 \$	2,999.00 x	
147	TRACK ROD ?	1 \$	157.00 ?	
148	TIE ROD END - RH ?	1 \$	217.00 ?	
149	ENGINE UNDERSHIELD <i>torn</i>	1 \$	709.00 ✓	<i>slg</i>
150	FRONT WINDSCREEN <i>cracked</i>	1 \$	1,875.00 ✓	
151	GEL FOIL FOR RAIN SENSOR <i>new</i>	1 \$	130.00 ✓	
152	GLASS PRIMER <i>new</i>	1 \$	22.00 ✓	
153	FRONT WINDSCREEN SEALANT <i>new</i>	S/N \$	200.00 ✓	
154	FRONT NO PLATE <i>new</i>	S/N \$	60.00 ✓	
155	ARYLIC SEALANT ?	S/N \$	180.00 ✓	
156	CAVITY WAX ?	S/N \$	140.00 ✓	
157	STONE CHIP ?	S/N \$	180.00 ✓	
158	METAL FILLER POWDER <i>new</i>	S/N \$	280.00 ✓	
159	RHS FRONT TYRE <i>new</i> (<i>\$410</i>)	S/N	TBC	<i>given by Adrian 23/2</i>
160	SUNDRIES ?	\$	600.00 ?	
TOTAL SPARE PARTS		:	\$ 102,291.00	
TOTAL LABOUR CHARGES		:	\$ 35,724.00	
GRAND TOTAL		:	\$ 138,015.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian L
23/02/22

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

ABE Authorised, 21 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT