



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300966

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 18/02/2023
Reference CC6/CTI22001788/Kpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SFS 3688A
Insured Veh. YQ 4278D
Claim No. SNM22D201370/C02
Policy No. DMCVSNA00119112101
Accident Date 23/02/2022
Inspection Date 24/02/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22001788/Kpa3q2 Date: 18/02/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 4278D	Veh. Inspected	SFS 3688A	
Policy No.	DMCVSNA00119112101	Coverage (\$)	0.00	
Claim No.	SNM22D201370/C02	Excess (\$)	0.00	
Assign From		Assign Date	24/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	LAND ROVER DISCOVERY (A)	c.c	2993	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	SALLAAAG5EA701158	Colour	METALLIC LIGHT BROWN	
Odometer	102018 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/55 R19	GOODYEAR	5 mm	
L/H Front Tyre	255/55 R19	GOODYEAR	5 mm	
R/H Rear Tyre	255/55 R19	GOODYEAR	4 mm	
L/H Rear Tyre	255/55 R19	GOODYEAR	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/02/2022	Inspection Date	24/02/2022	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFS 3688A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	N/S SIDE MIRROR LAMP	CUT	344.00	344.00
1	REAR N/S DOOR	BENT	5,480.00	5,150.00
1	REAR N/S DOOR ARCH PROTECTOR	BUCKLED	310.00	310.00
10	N/S ARCH PROTECTOR CLIP @\$8.00	NECESSARY	80.00	80.00
1	REAR N/S DOOR PROTECTOR RUBBER	NECESSARY	155.00	155.00
1	REAR N/S FENDER ARCH PROTECTOR	BUCKLED	370.00	370.00
1	REAR N/S DOOR OUTER HANDLE	BROKEN	1,100.00	1,100.00
1	N/S DOOR OUTER HANDLE KNOB	MISSING	85.00	85.00
2	N/S DOOR OUTER HANDLE SEAL @\$54.00	NECESSARY	108.00	108.00
1	N/S DOOR HANDLE REINFORCEMENT	DISTORTED	360.00	360.00
1	N/S DOOR HANDLE INNER STOPPER	NECESSARY	8.00	8.00
1	REAR N/S DOOR HANDLE CABLE (IN)	DENTED	55.00	55.00
1	REAR N/S DOOR HANDLE CABLE (OUT)	DENTED	60.00	60.00
	LESS 10% DISCOUNT		-851.50	-818.50
			7,663.50	7,366.50
1	REAR N/S DOOR RUBBER (50%) (SN)	NECESSARY	290.00	145.00
	LESS 10% DISCOUNT		-29.00	-
			261.00	145.00
	<u>LABOUR</u>			
	TO PUTTY AND SPRAY REPLACED PARTS.		1,200.00	800.00
	TO REMOVE CUT-OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN REFIX AND TO RENEW ABOVE PARTS.		700.00	500.00
			1,900.00	1,300.00
	GRAND TOTAL		9,824.50	8,811.50

Report Ref No. CC6/CTI22001788/Kpa3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,000.00
---	--	--	----------

Report Ref No. CC6/CTI22001788/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFS 3688A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFS 3688A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFS 3688A

RE-INSPECTION

