

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : YQ4278D
Accident Date : 23-Feb-2022

Our Ref : 022035 (CHINA) / CHAN

LOW KAR WOH KENNETH
31 OLD UPPER THOMSON ROAD
Singapore 576224

Not Withheld
1/1 Rm & 700ch
Penalty After Paint
4 days

No. : 06544

Date : 24-Feb-2022

PAGE : 1

ESTIMATED COST OF REPAIR FOR LAND ROVER DISCOVERY SFS3688A

1 pc N/s side mirror lamp
1 pc Rear n/s door
1 pc Rear n/s door rubber
1 pc Rear n/s door arch protector
10 pcs N/s arch protector clip @ S\$ 8.00
1 pc Rear n/s door protector rubber
1 pc Rear n/s fender arch protector
1 pc Rear n/s door outer handle
1 pc N/s door outer handle knob
2 pcs N/s door outer handle seal @ S\$ 54.00
1 pc N/s door handle reinforcement
1 pc N/s door handle inner stopper
1 pc Rear n/s door handle cable(In)
1 pc Rear n/s door handle cable(Out)

LBFA 780190-24630
Gr 344.00
Br 5,480.00
mi 290.00
Br 310.00
mi 80.00
mi 155.00
Br 370.00
Br 1,100.00
mi 85.00
mi 108.00
Di 360.00
mi 8.00
Di 55.00
Di 60.00

8,805.00

Less 10% : 880.50

7,924.50

To putty and spray replaced parts

1,200.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

700.00

Total : S\$ 9,824.50

Singapore Dollars Nine Thousand Eight Hundred
and Twenty Four and Cents Fifty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: