

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrotauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **GX 2192G**
Made : Toyota
Model : Dyna
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Rear Tailgate	1	\$ 1,987.63	\$ 1248.00 1,987.63	DDV
2	Rear Tailgate "Dyna" Sticker	1	\$ 204.50	\$ 78.10 204.50	NEC
3	Rear Tailgate Hinge	4	\$ 148.20	\$ 592.80	NNX
4	Rear Tailgate Side Lock RH	1	\$ 298.90	\$ 157.20 298.90	} BTV
5	Rear Tailgate Side Lock LH	1	\$ 298.90	\$ 157.20 298.90	
6	Rear Tailgate Stopper Bracket RH	1	\$ 210.00	\$ 69.90 210.00	BTV
7	Rear Tailgate Stopper Rubber RH	1	\$ 65.00	\$ 38.60 65.00	MIS
8	Rear Tailgate Stopper Bracket LH	1	\$ 210.00	\$ 69.90 210.00	BTV
9	Rear Tailgate Stopper Rubber LH	1	\$ 65.00	\$ 38.60 65.00	MIS
10	Rear Tailgate Lower Panel	1	\$ 1,347.40	\$ 1,347.40	NDX
11	Rear Taillamp Assembly RH	1	\$ 299.00	\$ 222.70 299.00	BRV
12	Rear Taillamp Bracket RH	1	\$ 259.00	\$ 105.10 259.00	BTV
13	Rear Taillamp Assembly LH	1	\$ 299.00	\$ 299.00	NDX
14	Rear Taillamp Bracket LH	1	\$ 259.00	\$ 259.00	NDX
15	Rear Number Plate Bracket	1	\$ 291.40	\$ 123.10 291.40	BTV
16	Rear Number Plate Lamp	1	\$ 139.20	\$ 123.10 139.20	BRV
17	Rear Spare Tyre Bracket	1	\$ 219.00	\$ 219.00	NDX
18	Rear Exhaust Pipe	1	\$ 895.00	\$ 585.20 895.00	BTV
19	Rear Exhaust Pipe Mounting	1	\$ 138.00	\$ 66.50 138.00	BRV
20	Rear Mudguard RH	1	\$ 343.00	\$ 290.00 343.00	BTV
21	Rear Mudflap RH	1	\$ 114.20	\$ 87.90 114.20	BTV
22	Rear Mudguard LH	1	\$ 343.00	\$ 343.00	} NDX
23	Rear Mudflap LH	1	\$ 114.20	\$ 114.20	
24	Rear Side Gate RH	1	\$ 2,468.70	\$ 1485.00 2,468.70	} DDV
25	Rear Side Gate LH	1	\$ 2,468.70	\$ 1485.00 2,468.70	
26	Rear Shock Absorber RH	1	\$ 276.00	\$ 276.00	} NDX
27	Rear Shock Absorber LH	1	\$ 276.00	\$ 276.00	
28	Rear Leaf Spring RH	1	\$ 728.00	\$ 728.00	
29	Rear Leaf Spring LH	1	\$ 728.00	\$ 728.00	

Parts Sub Total : \$6431.10 15,938.53

25% Discount \$1607.78 3,984.63

PARTS TOTAL : \$ 11,953.90

4823.33

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate	1	\$ 80.00	\$ 80.00 40.00
2	Rear Reverse Sensor	1	\$ 250.00	\$ 250.00
3	Rear Reverse Camera	1	\$ 500.00	\$ 500.00
4	Rear Tailgate "70km/h" Sticker	1	\$ 50.00	\$ 50.00 10.00
5	Rear Tailgate "6 Pax" Sticker	1	\$ 50.00	\$ 50.00 10.00
6	Rear Tailgate "Toyota" Sticker	1	\$ 200.00	\$ 200.00 30.00
7	Rear Step Bracket	1	\$ 450.00	\$ 450.00
8	Rear Floor Panel Wooden Plank	1	\$ 1,800.00	\$ 1,800.00
9	Rear Tailgate Lower Panel Sealant	1	\$ 150.00	\$ 150.00
10	Rear Tailgate Sealant	1	\$ 150.00	\$ 150.00
SPECIAL NETT TOTAL :				\$ 90.00 3,680.00

Nos.	LABOUR	S\$
1	To Panel Beat, Remove & Refix Parts	\$ 1,600.00 600.00
2	To Spray Paint Affected Areas	\$ 1,600.00 600.00
3	Wiring & Bulb Check	\$ 100.00
4	To Remove & Refix Rear Reverse Sensor	\$ 120.00
5	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 400.00
6	To apply anti rust on affected parts	\$ 120.00
7	To Conduct Water Leak Test	\$ 100.00
8	To Conduct Wheel Alignment	\$ 150.00
9	To Remove & Refix Rear Exhaust Pipe	\$ 120.00 50.00
LABOUR TOTAL :		\$ 1250.00 4,390.00

Survey 25/2/2022
1410 hrs
No Resurvey necessary, all external damages only.

TGtim

Lump sum repair
Repair days 5

PARTS TOTAL : \$ 11,953.90
SPECIAL NETT TOTAL : \$ 3,680.00
LABOUR TOTAL : \$ 4,390.00
GRAND TOTAL : \$ 20,023.90

Parts 4823.33
SN 90.00
Labour 1250.00

6163.33
@ 200% 1232.67
4930.66

LS 4,950/2

TGtim Min
15/3/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____