14	<	1	of 2 ?	>	Þ١	$\bigcirc$	€	100%	~		Ġ	Find   Next	
----	---	---	--------	---	----	------------	---	------	---	--	---	-------------	--



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	ale Des Experts En	Automob	pile							
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR22001802/Vqf3							
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 7705		Date:	24/02/2022							
				Code:	SMR							
1.	Policy Particulars :- (THIRD PARTY CLAIM)											
	Insured Veh.	SHB 5681X	Veh. Inspected	i	SMZ 1976L							
	Policy No.		Coverage (\$)		0.00							
	Claim No.	TAX/02/22/2064	Excess (\$)		0.00							
	Assign From	HUA YEN	Assign Date		24/02/2022							
2.		Vehicle Partic	ulars & Conditi	on								
	Make & Model		c.c		0							
	Engine No.	HIDDEN	Year of Reg.									
	Chassis No.		Colour									
	Odometer	-	Steering									
	Brakes		Modification									
	General											
3.		Condition	ons of Tyres									
		Size	Make		Balance							
	R/H Front Tyre				mm							
	L/H Front Tyre				mm							
	R/H Rear Tyre				mm							
	L/H Rear Tyre				mm							
4.		Descriptio	n of Damages									
					·							
5.		General										
	Accident Date	24/02/2022	Inspection Dat	te	25/02/2022							
	Survey held at	CARSMITH PTE LTD										
		BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807										
5a.		Remarks										
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.											