

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : ANG AI CHAN
275 TOH GUAN ROAD
#05-147
SINGAPORE (600275)

Claim No: MCS1900586
No: MFS1900548
Date: 13 Jun 2022
Policy No: P10658583R00
Veh Reg No: SMU2099M
Make/Model: HONDA VEZEL
Chassis No: RU11206660
TP Ins Co: GREAT

ATTN:
Your Ref No: SMU2099M
Claim Type: Third Party
Accident Date: 21/02/2022
TP Veh Reg No: GBL5005S

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SMU2099M

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 TAILGATE	1 PC	997.30	
2 VEZEL BADGE	1 PC	43.00	
3 TAIL END PANEL INNER TRIM BOARD	1 PC	92.30	
4 TAILGATE LAMP RH	1 PC	419.10	
5 REAR BUMPER	1 PC	553.10	
6 REAR BUMPER CLIPS	10 PC	38.00	
7 REAR WINDSCREEN MOULDING 1 SET	1 PC	118.30	
		2,261.10	
	Less 20%	452.22	1,808.88
Special Nett			
8 WINDSCREEN SEALANT	2 PC	30.00	
		30.00	30.00
LABOUR			
9 TO CHECK WIRING AND REINSTALL REVERSE SENSOR	1 PC	20.00	
10 TO DISMANTLE AND INSTALL REAR WINDSCREEN	1 PC	120.00	
11 TO DISMANTLE AND REPLACE TAILGATE, TRANSFER TAILGATE INNER PARTS, WIRING AND TRIM BOARD	1 PC	60.00	
12 TO DISMANTLE AND REPLACE DAMAGE PARTS, TO CUT, KNOCK AND WELD TAIL END PANEL, KNOCK AND REPAIR REAR AFFECTED AREA AND REFIT LISTED PARTS BACK SAME	1 PC	400.00	
13 TO SPRAY TAILGATE, REAR BUMPER SIDE PAD RH, REAR BUMPER SIDE PAD LH, TAIL END PANEL, TAILGATE CENTRE GARNISH AND APPLY SEALANT	1 PC	420.00	
		1,020.00	1,020.00

AH LIM MOTOR COMPANY
(SIN MIND BRANCH)

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : ANG AI CHAN
275 TOH GUAN ROAD
#05-147
SINGAPORE (600275)

ATTN:
Your Ref No: SMU2099M
Claim Type: Third Party
Accident Date: 21/02/2022
TP Veh Reg No: GBL5005S

DRAFT FINALISATION

Claim No: MCS1000586
No: MFST900548
Date: 13 Jun 2022
Policy No: P10658583R00
Veh Reg No: SMU2099M
Make/Model: HONDA VEZEL
Chassis No: RU11206660
TP Ins Co: GREAT

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SMU2099M

Description	Quantity	List Price	Amount
		S\$	S\$
	Total		S\$ 2,858.88
	Lump Sum Less 20%		-571.78
	Sub Total		S\$ 2,287.10
	Less Rounding		-37.10
	Lum Sum Repair		S\$ 2,250.00
	Add GST @ 7%		157.50
	Total Amount Payable		S\$ 2,407.50

TOTAL: SINGAPORE DOLLAR TWO THOUSAND FOUR HUNDRED AND SEVEN AND CENTS FIFTY ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 25/02/2022

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
(SIN MING BRANCH)
176, Sin Ming Drive, #05-12
Sin Ming Autocare Singapore 575721
Tel: 6456 3637 Fax: 6456 3686
AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S: ANG AI CHAN
275 TOH GUAN ROAD
#05-147
SINGAPORE (600275)

Estimate No: MCS1900586
Date: 22 Feb 2022
Policy No: P10658583R00
Veh Reg No: SMU2099M
Make/Model: HONDA VEZEL

ATTN:
Your Ref No: SMU2099M
Claim Type: Third Party
Accident Date: 21/02/2022
TP Veh Reg No: GBL5005S

Not Authorized
11 Day 8
Permy After Rain

4 days

Estimate Repair Cost to Vehicle No :SMU2099M

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 TAILGATE	1 PC	997.30	✓
2 TAILGATE CENTRE GARNISH	1 PC	220.70	?
3 VEZEL BADGE	1 PC	43.00	✓
4 TAILGATE RUBBER SEAL	1 PC	96.80	?
5 TAILGATE INNER LOCK	1 PC	98.50	?
6 TAIL END PANEL	1 PC	411.80	X
7 TAIL END PANEL INNER TRIM BOARD	1 PC	92.30	?
8 TAILGATE LAMP LH/RH	2 PC	838.20	?
9 REAR BUMPER	1 PC	553.10	✓
10 REAR BUMPER CLIPS	10 PC	38.00	—
11 REAR WINDSCREEN MOULDING 1 SET	1 PC	118.30	—
12 REAR BUMPER PLATE LAMP LH/RH	2 PC	77.00	X
		3,585.00	
	Less 20%	717.00	2,868.00
Special Nett			
13 NO PLATE	1 PC	35.00	X
14 WINDSCREEN SEALANT	2 PC	30.00	✓
15 REVERSE SENSOR 1 SET	1 PC	220.00	X
		285.00	285.00
LABOUR			
16 TO CHECK WIRING AND REINSTALL REVERSE SENSOR	1 PC	20.00	✓
17 TO DISMANTLE AND INSTALL REAR WINDSCREEN	1 PC	120.00	✓
18 TO DISMANTLE AND REPLACE TAILGATE, TRANSFER TAILGATE INNER PARTS, WIRING AND TRIM BOARD	1 PC	80.00	601
19 TO DISMANTLE AND INSTALL REAR CUSHION SEAT, SEATBELT AND INNER BOX	1 PC	60.00	?
20 TO DISMANTLE AND REPLACE DAMAGE PARTS, TO CUT, KNOCK AND WELD TAIL END PANEL, KNOCK AND REPAIR REAR AFFECTED AREA AND REFIT LISTED PARTS BACK SAME	1 PC	850.00	4001
21 TO SPRAY TAILGATE, REAR BUMPER SIDE PAD RH, REAR BUMPER SIDE PAD LH, TAIL END PANEL, TAILGATE CENTRE GARNISH AND APPLY SEALANT	1 PC	850.00	4201
		1,980.00	1,980.00

AH LIM MOTOR COMPANY
(SIN MING BRANCH)
176, Sin Ming Drive, #05-12
Sin Ming Autocare, Singapore 575721
Tel: 6456 3637 Fax: 6456 3686