14	<	1	of 2 ?	>	Þ١	Ö	⊕	100%	~		Ġ	Find Next	
----	---	---	--------	---	----	---	----------	------	---	--	---	-------------	--



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	ale Des Experts En A	Automob	ile							
	MS FIRST CAPITA	L INSURANCE LTD	F	Ref:	CS3/FCI22001816/Rqf3							
	36 ROBINSON RO	AD SESINGAPORE 068877]	Date:	25/02/2022							
			(Code:	FCI2							
١.	Policy Particulars :- (THIRD PARTY CLAIM)											
	Insured Veh.	SMB 5063X	Veh. Inspected		YP 5047C							
	Policy No.		Coverage (\$)		0.00							
	Claim No.	D22000550MFBP	Excess (\$)		0.00							
	Assign From	HARMINDER KAUR	Assign Date		25/02/2022							
2.	Vehicle Particulars & Condition											
	Make & Model		c.c		0							
	Engine No.	HIDDEN	Year of Reg.									
	Chassis No.											
	Odometer	-	Steering									
	Brakes		Modification									
	General											
3.		Condition	ons of Tyres									
		Size	Make		Balance							
	R/H Front Tyre				mm							
	L/H Front Tyre				mm							
	R/H Rear Tyre				mm							
	L/H Rear Tyre				mm							
١.	Description of Damages											
5.		General Information										
	Accident Date	21/02/2022	Inspection Date)	25/02/2022							
	Survey held at	Sin Ming Rd opp Blk 10 URA hea	•									
	Repairer	TAN HUP SENG AUTO REPAIR	WORKSHOP									
ia.	Remarks											
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.											