



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2204661

INV Date 28/07/2022

Reference CC4/LPC22001817/Epa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLJ 9065J
Insured Veh. YQ 614T
Claim No. 21/22/22/VC05/025430
Policy No. Z21VC05007032
Accident Date 07/02/2022
Inspection Date 02/03/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22001817/Epa3q2 Date: 28/07/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 614T	Veh. Inspected	SLJ 9065J	
Policy No.	Z21VC05007032	Coverage (\$)	0.00	
Claim No.	21/22/22/VC05/025430	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	25/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLVO S60	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	YV1FS28C0H2432056	Colour	WHITE	
Odometer	74964 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R16	MICHELIN	5 mm	
L/H Front Tyre	215/55 R16	MICHELIN	5 mm	
R/H Rear Tyre	215/55 R16	MICHELIN	5 mm	
L/H Rear Tyre	215/55 R16	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/02/2022	Inspection Date	02/03/2022	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 9065J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR S6 (SN)	DENTED	2,087.70	1,878.93
1	TOW COVER REAR S60 1 (SN)	MISSING	89.80	80.82
1	BUMPER SPOILER REAR (SN)	BROKEN	590.40	531.36
1	PROTECTING PLATE REA (SN)	NOT NECESSARY	538.40	-
1	BUMPER BRACKET CTR R (SN)	NOT NECESSARY	167.10	-
1	BUMPER BRACKET REAR (SN)	NOT NECESSARY	66.10	-
1	BUMPER BRACKET REAR (SN)	NOT NECESSARY	66.10	-
1	BUMPER BRACKET REAR (SN)	NOT NECESSARY	44.60	-
1	BUMPER BRACKET RHR S (SN)	NOT NECESSARY	66.10	-
1	BUMPER INSTALLING MT (SN)	NECESSARY	101.40	91.26
10	BUMPER CLIP 8X8,5 (SN)	NECESSARY	82.00	73.80
10	CLIP XC90 16- XC60 (SN)	NECESSARY	88.00	79.20
1	EMBLEM 'VOLVO' REAR (SN)	NOT NECESSARY	121.80	-
1	EMBLEM 'S60' CH 1700 (SN)	NOT NECESSARY	112.30	-
1	EMBLEM 'T2' S60 16- (SN)	NOT NECESSARY	112.30	-
4	PARKING SENSOR 29DB (SN)	NOT NECESSARY	942.40	-
1	CABLE HARNESS REAR B (SN)	NOT NECESSARY	133.80	-
1	BUMPER RAIL REAR S60 (SN) (ADDITIONAL)	DENTED	1,459.44	1,459.44
			6,869.74	4,194.81
	<u>LABOUR</u>			
	TO REPLACE REAR BOOT LID ,REAR EMBLEM ,REAR BUMPER ,REAR LOWER SPOILER ,ETC.		2,550.00	850.00
	TO PUTTY SPRAY PAINT ON REAR BOOT LID ,REAR BUMPER ,REAR LOWER SPOILER ,ETC.		3,000.00	750.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		540.00	540.00
			6,090.00	2,140.00
	GRAND TOTAL		12,959.74	6,334.81



RECOMMENDED COST OF REPAIRS			6,334.81
------------------------------------	--	--	-----------------

Report Ref No. CC4/LPC22001817/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLJ 9065J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLJ 9065J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

