

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623 Code: SMO 1. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SKC 998A Veh. Inspected SKT 9877S Policy No. Coverage (\$) 0.00 Claim No. CMTD2200703/MYE Excess (\$) Assign From GRACE TEO Ref: CS/SMO220018 Ref: CS/SMO220018 Date: 11/03/2022	820/Uqf3n2	
SINGAPORE LAND TOWERSINGAPORE 048623 Code: SMO 1. Policy Particulars: - THIRD PARTY CLAIM Insured Veh. SKC 998A Veh. Inspected SKT 9877S Policy No. Coverage (\$) 0.00 Claim No. CMTD2200703/MYE Excess (\$) 0.00		
Insured Veh. SKC 998A Veh. Inspected SKT 9877S Policy No. Coverage (\$) 0.00 Claim No. CMTD2200703/MYE Excess (\$) 0.00		
Insured Veh. SKC 998A Veh. Inspected SKT 9877S		
Policy No. Coverage (\$) 0.00 Claim No. CMTD2200703/MYE Excess (\$) 0.00		
Claim No. CMTD2200703/MYE Excess (\$) 0.00		
Assign From GRACE TEO Assign Date 25/02/2022		
Assign Form Process Assign Date 25/02/2022		
2. Vehicle Particulars & Condition		
Make & Model VOLVO S60 (A) c.c 1560		
Engine No. HIDDEN Year of Reg. 2015		
Chassis No. YV1FS84ABF2367490 Colour RED		
Odometer 200011 KM Steering IN ORDER		
Brakes IN ORDER Modification SPORTS RIM		
General GOOD		
3. Conditions of Tyres		
Size Make Balance		
R/H Front Tyre 215/55 R16 YOKOHAMA 6 mm		
L/H Front Tyre 215/55 R16 YOKOHAMA 6 mm		
R/H Rear Tyre 215/55 R16 YOKOHAMA 6 mm		
L/H Rear Tyre 215/55 R16 YOKOHAMA 6 mm		
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.		
DAMAGES SEE DETAILS.		
5. General Information		
Accident Date 23/02/2022 Inspection Date 25/02/2022		
Survey held at IMPERIUM AUTOMOTIVE		
25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks		
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days		