

ESTIMATE
T&C AUTOMOTIVE
1 KAKI BUKIT AVENUE 6 #01-68 AUTOBAY@KAKI BUKIT SINGAPORE 417883
CONTACT PERSON: AH CHAI
CONTACT NUMBER: 9007 5148

WAUZZZ8TOBA 009985

TP Chuan, TP MS16

Hui Rong

Vehicle Number:	SMQ2183Z	Vehicle Model:	AUDI S5
-----------------	----------	----------------	---------

No	List Of Items	Amount SGD
1	Front Bonnet <i>Repl</i>	\$ 2,249.00 <i>x</i>
2	Front Bonnet Insulator <i>3 new</i>	\$ 288.00 <i>x</i>
3	Front Bonnet Catch Hook	\$ 135.00 <i>x</i>
4	Front Bonnet Edge Protection x 2 <i>3 new</i>	\$ 68.00 <i>x</i>
5	Front Bonnet Lid Lock with Micro Switch	\$ 288.00 <i>x</i>
6	Front Bumper <i>Distorted</i>	\$ 2,138.00 <i>✓</i>
7	Front Bumper Reinforcement <i>Not new</i>	\$ 880.00 <i>x</i>
8	Front Bumper Support x 2 <i>RT cracked</i>	\$ 88.00 44.00 <i>✓</i>
9	Front Bumper Fog Lamp RHS <i>cracked</i>	\$ 299.80 <i>✓</i>
10	Front Bumper Fog Lamp Cover RHS <i>Missing</i>	\$ 168.50 <i>✓</i>
11	Front Bumper Nozzle Cover <i>Missing</i>	\$ 120.00 <i>✓</i>
12	Front Bumper Tow Cover <i>Not new</i>	\$ 48.00 <i>x</i>
13	Front Bumper Sensor x 2 <i>1 piece damaged</i>	\$ 440.00 220.00 <i>✓</i>
14	Front Bumper Sensor Holder x 4 <i>new</i>	\$ 80.00 <i>✓</i>
15	Front Grille 'QUATTRO' <i>cracked</i>	\$ 2,240.00 1680.00 <i>✓</i>
16	Front Grille Logo <i>3 new</i>	\$ 128.00 <i>✓</i>
17	Front Grille 'S5' Emblem	\$ 118.00 <i>✓</i>
18	Front Support Panel <i>cracked</i>	\$ 1,127.00 <i>✓</i>
19	Oil Cooler <i>Not new</i>	\$ 829.00 <i>x</i>
20	Aircon Condensor <i>Not new</i>	\$ 1,320.00 <i>x</i>
21	Secondary Air Pump <i>cracked</i>	\$ 1,047.90 <i>✓</i>
22	Secondary Air Pump Upper Hose <i>3 new</i>	\$ 199.80 <i>x</i>
23	Secondary Air Pump Lower Hose	\$ 199.80 <i>x</i>
24	Front Headlamp RHS <i>cracked</i>	\$ 2,578.10 <i>✓</i>
25	Front Headlamp Lower Bracket RHS <i>Not new</i>	\$ 198.00 <i>x</i>
26	Front Headlamp Nozzle <i>cracked</i>	\$ 220.00 <i>✓</i>
27	Front Fender RHS <i>Dented</i>	\$ 980.00 <i>✓</i>
28	Front Fender Inner Shield <i>torn</i>	\$ 260.00 195.00 <i>✓</i>
TOTAL		\$ 18,435.80

11144.20
Len 10%: 10029.78

Special Nett Items

1	Bonnet Insulator Clip Set <i>Not new</i>	\$ 60.00 <i>x</i>
2	Bumper Clip Set <i>new</i>	\$ 60.00 30.00 <i>✓</i>
3	Front Number Plate with Holder <i>Not new</i>	\$ 60.00 <i>x</i>
4	Fender Inner Shield Clip Set <i>new</i>	\$ 60.00 30.00 <i>✓</i>
5	Radiator Coolant <i>Not new</i>	\$ 100.00 <i>x</i>
TOTAL SPECIAL NETT		\$ 340.00

60

Vehicle Number:

SMQ2183Z

Vehicle Model:

AUDI S5

Labour Charges

1	Towing service	\$	150.00	X
2	To check wiring and lighting	\$	80.00	30
3	To remove, replace and refix front bumper sensor	\$	100.00	50
4	To remove and refix radiator assy	\$	150.00	X
5	To remove, refix and top up aircon gas	\$	150.00	X 160
6	To apply anti-rust proofing on affected areas	\$	100.00	30
7	To perform diagnostic check for fault codes and reset factory settings	\$	250.00	X 100
8	To panel beat and replace damaged parts on affected areas	\$	1,800.00	900
9	To putty and spray paintings on affected areas	\$	1,800.00	600
TOTAL LABOUR		\$	4,580.00	

ESTIMATE PARTS AND LABOURS GRAND TOTAL

\$ 23,355.80

total 11899.78

H/S: 9.51c

06 Days.

9.51c.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: