



PORSCHE

Page 1 of 2

	REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.				
2	TO RESPRAY FORNT BUMPER .				\$ 1,500.00
3	TO SUPPLY FRONT LICENCE PLATE WITH CASING			NETT	\$ 70.00
4	TO APPLY SPECIAL CERAMIC COATING. (PROCE TO BE ADVISE)			NETT	
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				\$ 250.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			NETT	\$ 600.00
7	SUNDRIES.			NETT	\$ 50.00
		TOTAL LABOUR		\$ -	\$ 5,590.00
		TOTAL PARTS		\$ -	\$ 5,177.90
		TOTAL		\$ -	\$ 10,767.90
		LESS EXCESS		\$ -	\$ -
		TOTAL AFTER EXCESS		\$ -	\$ 10,767.90
		GST 7%		\$ -	\$ 753.75
		GRAND TOTAL		\$ -	\$ 11,521.65

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

XE9090U

Date of Accident

19/02/2022 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance Lonpac Insurance Bhd

Period of Insurance 29/10/2021 - 28/10/2022

Requested By STUTTGART AUTO PTE LTD - T...

Requested Date 21/02/2022 14:50

Payment details

Request Amount: **\$S\$1.87**GST Amount: **\$S\$0.13**Total Amount Due (GST Inclusive): **\$S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**