

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI22001834/VVF3N2**Date:** 21/03/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000276
<b>Claimant Vehicle No :</b>	SHC8640P	<b>Insured Vehicle No :</b>	SLQ3924H
Date of Loss:	25/02/2022	Nature of Claim:	TP
		Claim No:	M2200988

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC8640P</b>	Engine No:	D4FDEU410568
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMGU082989
Reg. Date:	29/12/2015 (Man. Year: 2015)	Odometer:	556479 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	206/60R16	Rear Tyre Size:	206/60R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,553.30	2,940.26	1,613.04	35.43
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,920.00	1,090.00	830.00	43.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,484.30</b>	<b>4,041.26</b>	<b>2,443.04</b>	<b>37.68</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,250.00</b>		
<b>(S\$)</b>	6,484.30	3,250.00	3,234.30	49.88
<b>+ GST 7.00/7.00% (S\$)</b>	453.90	227.50	226.40	49.88
<b>Nett Amount (S\$)</b>	<b>6,938.20</b>	<b>3,477.50</b>	<b>3,460.70</b>	<b>49.88</b>

INSPECTION

Date of Assignment:	25/02/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	25/02/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2022)
<b>Parts:</b> 143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC8640P)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BOOTLID	Bent	2,609.80 FL	-	*2,609.80 FL
2	1		*BOOTLID H EMBLEM	Necessary	63.10 FL	-	*63.10 FL
3	1		*BOOTLID CRDI EMBLEM	Necessary	52.40 FL	-	*52.40 FL
4	1		*BOOTLID I40 EMBLEM	Necessary	67.90 FL	-	*67.90 FL
5	1		*BOOTLID OUTER GARNISH	Serviceable	227.90 FL	-	*- FL
6	1		*REAR BUMPER	Cut	553.00 FL	-	*553.00 FL
7	1		*REAR BUMPER REINFORCEMENT	Serviceable	428.40 FL	-	*- FL
8	1		*REAR BUMPER SPONGE	Serviceable	119.50 FL	-	*- FL
9	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
10	2		*REAR BUMPER REINFORCEMENT BRACKET RH / LH	Serviceable	160.60 FL	-	*- FL
11	1		*REAR END PANEL	Serviceable	526.70 FL	-	*- FL
12	1		*REAR END LOWER PANEL	Serviceable	495.50 FL	-	*- FL
13	1		*REAR END GARNISH	Serviceable	57.70 FL	-	*- FL
14	1		*REAR BUMPER MAT	Necessary	50.00 F	-	*50.00 FS
15	1		*REVERSE SENSORS	Cut	135.70 F	-	*135.70 FS
16	1		*BOOTLID COMFORTDELGRO STICKER	Necessary	30.00 F	-	*30.00 FS
17	1		*BOOTLID 65521111 STICKER	Necessary	30.00 F	-	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,630.20</b>	<b>3,613.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,076.90	673.64
<b>Total Parts (\$\$)</b>	<b>4,553.30</b>	<b>2,940.26</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
			<b>Sub Total (\$\$)</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	900.00	560.00
2	SPRAY PAINTING	New	900.00	500.00
3	R/I REVERSE SENSORS	New	120.00	30.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,920.00</b>
				<b>1,090.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >