

REPAIR DETAILS	
<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 25 Feb 2022)
<b>Parts:</b> 143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> ComfortDelGro Engineering Pte Ltd/SHC8640P/25/02/2022 14:25	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*BOOTLID	20.00	0.00	*2,609.80 FL	XV BT
2	1		*BOOTLID H EMBLEM	20.00	0.00	*63.10 FL	n/c
3	1		*BOOTLID CRDI EMBLEM	20.00	0.00	*52.40 FL	n/c
4	1		*BOOTLID I40 EMBLEM	20.00	0.00	*67.90 FL	n/c
5	1		*BOOTLID OUTER GARNISH	20.00	0.00	*227.90 FL	XSVc
6	1		*REAR BUMPER	20.00	0.00	*553.00 FL	cut
7	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*428.40 FL	1. XSVc
8	1		*REAR BUMPER SPONGE	20.00	0.00	*119.50 FL	7. XSVc
9	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL	n/c
10	2		*REAR BUMPER REINFORCEMENT BRACKET RH / LH	20.00	0.00	*160.60 FL	7. XSVc
11	1		*REAR END PANEL	20.00	0.00	*526.70 FL	7. XSVc
12	1		*REAR END LOWER PANEL	20.00	0.00	*495.50 FL	7. XSVc
13	1		*REAR END GARNISH	20.00	0.00	*57.70 FL	7. XSVc
14	1		*REAR BUMPER MAT	0.00	0.00	*50.00 F	n/c
15	1		*REVERSE SENSORS	0.00	0.00	*135.70 F	cut
16	1		*BOOTLID COMFORTDELGRO STICKER	0.00	0.00	*30.00 F	n/c
17	1		*BOOTLID 65521111 STICKER	0.00	0.00	*30.00 F	n/c

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,630.20</b>
<b>- List Item Discount on L Items (\$)</b>	<b>1,076.90</b>
<b>Total Parts (\$)</b>	<b>4,553.30</b>

ComfortDelGro Engineering Pte Ltd/SHC8640P/25/02/2022 14:25. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00
<b>Sub Total (\$)</b>			<b>11.00</b>

Estimates on Labour

No	Particulars	Lab Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	900.00 560
2	SPRAY PAINTING	New	900.00 500
3	R/I REVERSE SENSORS	New	120.00 30
<b>Gross Labour Cost (\$)</b>			<b>1,920.00</b>

ComfortDelGro Engineering Pte Ltd/SHC8640P/25/02/2022 14:25 Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thruca  
822 3596 9  
25/2/22 1700  
L/S after repair photo  
3 days w/p

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: