

REG. NO:

Thevan

REF:

CS/TMI 220018.34/VUFS

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: **SLQ 3924H**  
 Policy No: **MN000276**  
 Claims No: **M2200988**  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     | X   |

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: **SLC 8640P** Yr Rogn: **29/12/15**  
 Type: M.Car / M.Cycle / Bus / Van / Lorry /  Taxi  / Primo Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: **Hyundai** 140 cc **1685**  
 Colour: **blue** VC: Insured / Std / NI / NA  
 Sp. Reading: **55647.9** T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **kmHLB414MG4082989**  
 Gen. Cond:  Good  / Fair / Poor / Burnt  
 Steering: In  order  / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In  order  / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil /  SRIM  / STD A/Rlm or \_\_\_\_\_  
 Tyro Size: F: **206/60R16**  
 R: **206/60R16**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Weslake**  
 Front **5** mm Rear **5** mm  
 R/Bal. **5** mm L/Bal. **5** mm  
 L/Bal. **5** mm U/Bal. **5** mm  
 D.O.A. **25/2/22** D.O.I. **25/2/22 1700**  
 Survey held at **CDGE**  
 Des. of Damages: Frt /  Rear  / OIS / NIS / UIC / Rooflop or \_\_\_\_\_

The UIC / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                         |
|-------------|--|
|             | NO GIA provided                              |
| 15/3/22     | Thevan informed LS \$3250 (Red 3234.30, 49%) |
|             |  |
|             |  |
|             |  |
|             |  |

Date/Time File Pass to?  : Prelim. Report  
 : Final Report

Days Of Repair: **3**  
 Resurvey No. of Trip: **2**

15/3/22-typist

Request Form No: **Merimen**  
 LS \$3250

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Wash & Clean (\$ \_\_\_\_\_)

Survey Fee:

|                 |          |
|-----------------|----------|
| Transportation: | _____    |
| S + RS:         | _____ \$ |
| Fuel:           | _____    |
| Office:         | _____    |
| Other:          | _____    |
| Total:          | _____    |

am: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 4178435

JC NO305506488


|                                   |  |   |
|-----------------------------------|--|---|
| OMER                              | REGN NO:<br><b>SHC8640P</b>              | MILEAGE                                 |
| IS COMFORT TRANSPORTATION PTE LTD | MAKE:<br><b>HYUNDAI</b>                  | FUEL<br>E.....1/2.....F                 |
| OMER NO. 7010045                  | MODEL<br><b>I-40</b>                     | DATE/TIME IN<br><b>25.02.2022 12:45</b> |
| RESS 383 SIN MING DRIVE           | YR OF MANU.<br><b>29.12.2015</b>         | TARGET DATE                             |
| Singapore SINGAPORE 575717        | CHASSIS CODE<br><b>KMHLB41UMGU082989</b> | COMPLETION DATE/TIME:                   |
| (R) 65508755 (O)                  |  |   |
| (P)                               |  |   |
| DUANT CARD NO.                    |  |   |

cident Date: 25.02.2022  
TURE: 3P 25.02.2022

JOB DESCRIPTION

NO 10010 LABOR CODE PB

DESCRIPTION  
LUMPSUM REPAIR-SHC8640P



KEYED & PASSED OUT BY: \_\_\_\_\_

\_\_\_\_\_  
SERVICE ADVISOR

\_\_\_\_\_  
CUSTOMER'S SIGNATURE

edgement Slip

lo.: **SHC8640P** **LIMITS**

Service Advisor \_\_\_\_\_ Signature/Date \_\_\_\_\_

urned to Service Reception upon collection

Exit Pass

Vehicle No.: **SHC8640P**

Name of Service Advisor \_\_\_\_\_ Date \_\_\_\_\_

To be kept by Security Guard

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W) **SAS-KW**  
 59 Loyang Drive  
 Singapore 508969  
 Tel: 6214 8300

**LKK-**

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**CTPL**  
 Singapore **(CLS)**

**PARTICULARS OF CLAIM**

|                               |  |                    |                   |
|-------------------------------|--|--------------------|-------------------|
| Claim Type:                   | THIRD PARTY                                | Ref. No:           |                   |
| Policy No:                    |  | Date of Loss:      | 25/02/2022        |
| Vehicle Reg. No.:             | <b>SHC8640P</b>                            | Driveable?         | NO                |
| Party At Fault:               | UNKNOWN                                    |                    |                   |
| Make/Model:                   | HYUNDAI I40, 1.7 D CRDI (A)                | Vehicle Reg. Date: | 29/12/2015        |
| Vehicle Colour:               | BLUE                                       | Gen Condition:     | GOOD              |
| Engine No:                    | D4FDEU410568                               | Chassis No:        | KMHLB41UMGU082989 |
| Odometer:                     | 0 KM                                       |                    |                   |
| Paint Type:                   |  |                    |                   |
| List Item Discount:           | 20.00 %                                    |                    |                   |
| Total Loss?                   | <b>NO</b>                                  |                    |                   |
| Est. Duration of Repair (day) | 4  |                    |                   |
| Present Location:             | COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) |                    |                   |

**COST OF CLAIMS**

**Amount**

|                          |                 |
|--------------------------|-----------------|
| Parts                    | 4,553.30        |
| Miscellaneous Items      | 11.00           |
| Labour                   | 1,920.00        |
| Paintwork Labour         | 0.00            |
| Towing                   | 0.00            |
| <b>Gross Total (S\$)</b> | <b>6,484.30</b> |
| <b>+ GST 7.00% (S\$)</b> | <b>453.90</b>   |
| <b>Nett Amount (S\$)</b> | <b>6,938.20</b> |

**This claim is handled by: LIM TIEN SIONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

### Estimates on Miscellaneous Items

| No                         | Qty | Particulars          | Amount       |
|----------------------------|-----|----------------------|--------------|
| <b>Miscellaneous Items</b> |     |                      |              |
| 1                          | 1   | OD/TP Case (Insurer) | 11.00        |
| <b>Sub Total (\$)</b>      |     |                      | <b>11.00</b> |

### Estimates on Labour

| No                            | Particulars         | Lab.Type | Amount            |
|-------------------------------|---------------------|----------|-------------------|
| <b>Labour Items</b>           |                     |          |                   |
| 1                             | PANEL BEATING       | New      | 900.00 <i>560</i> |
| 2                             | SPRAY PAINTING      | New      | 900.00 <i>500</i> |
| 3                             | R/I REVERSE SENSORS | New      | 120.00 <i>30</i>  |
| <b>Gross Labour Cost (\$)</b> |                     |          | <b>1,920.00</b>   |

ComfortDelGro Engineering Pte Ltd/SHC8640P/25/02/2022 14:25. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*Thruvan  
822 3576 9  
25/2/22 1700  
L/S after repair photo  
3 days wp*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised 25 Feb 2022)  
 Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: ComfortDelGro Engineering Pte Ltd/SHC8640P/25/02/2022 14:25  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*

Estimates on Parts

| No. | Qty | Part No. | Particulars                                | %Disc | %Depr | Amount                 |
|-----|-----|----------|--|-------|-------|------------------------|
| 1   | 1   |          | *BOOTLID                                   | 20.00 | 0.00  | *2,609.80 FL <i>XV</i> |
| 2   | 1   |          | *BOOTLID H EMBLEM                          | 20.00 | 0.00  | *83.10 FL <i>MC</i>    |
| 3   | 1   |          | *BOOTLID CRDI EMBLEM                       | 20.00 | 0.00  | *52.40 FL <i>MC</i>    |
| 4   | 1   |          | *BOOTLID I40 EMBLEM                        | 20.00 | 0.00  | *67.90 FL <i>MC</i>    |
| 5   | 1   |          | *BOOTLID OUTER GARNISH                     | 20.00 | 0.00  | *227.90 FL <i>XS4C</i> |
| 6   | 1   |          | *REAR BUMPER                               | 20.00 | 0.00  | *553.00 FL <i>4+</i>   |
| 7   | 1   |          | *REAR BUMPER REINFORCEMENT                 | 20.00 | 0.00  | *428.40 FL <i>?</i>    |
| 8   | 1   |          | *REAR BUMPER SPONGE                        | 20.00 | 0.00  | *119.50 FL <i>?</i>    |
| 9   | 10  |          | *REAR BUMPER CLIPS                         | 20.00 | 0.00  | *22.00 FL <i>MC</i>    |
| 10  | 2   |          | *REAR BUMPER REINFORCEMENT BRACKET RH / LH | 20.00 | 0.00  | *160.60 FL <i>?</i>    |
| 11  | 1   |          | *REAR END PANEL                            | 20.00 | 0.00  | *526.70 FL <i>?</i>    |
| 12  | 1   |          | *REAR END LOWER PANEL                      | 20.00 | 0.00  | *495.50 FL <i>?</i>    |
| 13  | 1   |          | *REAR END GARNISH                          | 20.00 | 0.00  | *57.70 FL <i>?</i>     |
| 14  | 1   |          | *REAR BUMPER MAT                           | 0.00  | 0.00  | *50.00 F <i>MC</i>     |
| 15  | 1   |          | *REVERSE SENSORS                           | 0.00  | 0.00  | *135.70 F <i>4+</i>    |
| 16  | 1   |          | *BOOTLID COMFORTDELGRO STICKER             | 0.00  | 0.00  | *30.00 F <i>MC</i>     |
| 17  | 1   |          | *BOOTLID 65521111 STICKER                  | 0.00  | 0.00  | *30.00 F <i>MC</i>     |

F=Franchise part, L=ListItemDisc.

|                                       |                 |
|---------------------------------------|-----------------|
| Sub Total (S\$)                       | 5,630.20        |
| - List Item Discount on L Items (S\$) | 1,076.90        |
| <b>Total Parts (S\$)</b>              | <b>4,553.30</b> |

ComfortDelGro Engineering Pte Ltd/SHC8640P/25/02/2022 14:25. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS