

COMFORTDELGRO ENGINEERING

COMFORTDELGRO ENGINEERING Pte Ltd
501, Orchard Road, Singapore 238883
Fax: 6546 8156

Our Job Ref No : 305506488
Date : 01/03/22

FINALIZATION FORM

To : LKK
Attn : THEVAN
Vehicle Reg No : S4C8640P

Fax:

Date of Accident : 25.02.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows -

1. The repair job shall bill to TOKIO MARINE - SLO3924H
2. The finalized amount shall be
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges (Include advertisement stickers etc./if any) _____
 - Total for Part-By-Part Repair Cost** _____
 - (c) Lumpsum Repair (if applicable) _____
 - Total for Lumpsum repair cost after Less: 20% \$3,250.00
 - Final Lumpsum Repair cost** \$3,250.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : THEVAN
Date : 15/3/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 25 Feb 2022)
Parts: 143 **HYUNDAI I40 1.7 D CRDi (A)** (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHC8640P/25/02/2022 14:25
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*BOOTLID	20.00	0.00	*2,609.80 FL	XV BT
2	1		*BOOTLID H EMBLEM	20.00	0.00	*63.10 FL	N/C
3	1		*BOOTLID CRDI EMBLEM	20.00	0.00	*52.40 FL	N/C
4	1		*BOOTLID I40 EMBLEM	20.00	0.00	*67.90 FL	N/C
5	1		*BOOTLID OUTER GARNISH	20.00	0.00	*227.90 FL	X Svc
6	1		*REAR BUMPER	20.00	0.00	*553.00 FL	cut
7	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*428.40 FL	1. X Svc
8	1		*REAR BUMPER SPONGE	20.00	0.00	*119.50 FL	7. X Svc
9	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL	N/C
10	2		*REAR BUMPER REINFORCEMENT BRACKET RH / LH	20.00	0.00	*160.60 FL	7. X Svc
11	1		*REAR END PANEL	20.00	0.00	*526.70 FL	7. X Svc
12	1		*REAR END LOWER PANEL	20.00	0.00	*495.50 FL	7. X Svc
13	1		*REAR END GARNISH	20.00	0.00	*57.70 FL	7. X Svc
14	1		*REAR BUMPER MAT	0.00	0.00	*50.00 F	N/C
15	1		*REVERSE SENSORS	0.00	0.00	*135.70 F	cut
16	1		*BOOTLID COMFORTDELGRO STICKER	0.00	0.00	*30.00 F	N/C
17	1		*BOOTLID 65521111 STICKER	0.00	0.00	*30.00 F	N/C

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,630.20
- List Item Discount on L Items (S\$)	1,076.90
Total Parts (S\$)	4,553.30

ComfortDelGro Engineering Pte Ltd/SHC8640P/25/02/2022 14:25. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab Type	Amount
Labour Items			
1	PANEL BEATING	New	900.00 ⁵⁶⁰
2	SPRAY PAINTING	New	900.00 ⁵⁰⁰
3	R/I REVERSE SENSORS	New	120.00 ³⁰
Gross Labour Cost (S\$)			1,920.00

ComfortDelGro Engineering Pte Ltd/SHC8640P/25/02/2022 14:25 Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuvai
822 3596 9
25/2/22 1700
L/S after repair photo
3 days wp

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: