

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22001835/EEA3Q2**Date:** 02/09/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MCV0002573_02
Claimant Vehicle No : SMT7271D **Insured Vehicle No :** GZ5360H
 Date of Loss: 23/02/2022 Nature of Claim: TP Claim No: MCV2022D0000953

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT7271D**
 Make & Model: MERCEDES-BENZ GLC300, 2.0 AMG LINE M-HYBRID (A) Engine No: 26492030206759
 Reg. Date: 15/07/2020 (Man. Year: 2019) Chassis No: WDC2533842F729050
 Colour: Red Odometer: 22535 km
 Engine Capacity: 1991 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/50 R19 Rear Tyre Size: 255/50 R19
 Front Left Side: 5 mm Rear Left Side: 5 mm
 Front Right Side: 5 mm Rear Right Side: 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,749.50	3,045.00	2,704.50	47.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	1,200.00	2,280.00	65.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,229.50	4,245.00	4,984.50	54.01
+ GST 7.00/7.00% (S\$)	646.07	297.15	348.92	54.01
Nett Amount (S\$)	9,875.57	4,542.15	5,333.42	54.01
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,949.60		

INSPECTION

Date of Assignment: 25/02/2022
 Date Inspected: 02/03/2022 Inspected At: MAXIMUS AUTO SERVICES PTE LTD
 7 Soon Lee Street, #05-05 MR Performance Centre
 Singapore 627608
 Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Jul 2022)	
Parts:	N/A	MERCEDES-BENZ GLC300 2.0 AMG LINE M-HYBRID (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT7271D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RIM -LEFT	Not Necessary	2,500.00 FL	*- FL
2	1		*REAR FENDER WHEEL ARCH TRIM -LEFT	Cut	250.00 FL	*250.00 FL
3	1		*REAR DOOR -LEFT	Dented	2,800.00 FL	*2,800.00 FL
4	1		*REAR DOOR HINGE UPPER -LEFT	Not Necessary	180.00 FL	*- FL
5	1		*REAR DOOR HINGE LOWER -LEFT	Not Necessary	200.00 FL	*- FL
6	1		*REAR DOOR SEAL -LEFT	Necessary	250.00 FL	*250.00 FL
7	1		*REAR DOOR DAMPING INSULATION	Necessary	50.00 FL	*50.00 FL
8	1		*SET MISCELLANEOUS-BOLTS ,NUTS ,SCREWS ,CLIPS,ETC	Necessary	150.00 FN	*30.00 F

F=Franchise part. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	6,380.00	3,380.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	623.00	335.00
- Nett Item Discount on N Items 5.00/0.00% (\$\$)	7.50	0.00
Total Parts (\$\$)	5,749.50	3,045.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & RENEW DAMAGED PARTS ,STRAIGHTEN & REALIGN AFFECTED AREAS	New	1,000.00	400.00
2	RESPRAY AFFECTED AREAS -HYINCINTH RED-MERCEDES PREMIUM COLOUR	New	1,500.00	500.00
3	LABOUR TO CHARGE WHEEL	New	60.00	0.00
4	COMPUTERISED WHEEL ALIGNMENT SERVICE	New	120.00	0.00
5	DR BEASLEYS VEICLE COATING NANO PRO RESIN COATING	New	800.00	300.00
Gross Labour Cost (\$)			3,480.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >